# IGNITION COILS

Original Equipment Quality (ISO/IATF16949 Compliant)

# IGNITION COILS



| Part No.: | Application: |
|---|---|
| **PIC01** | **Honda**<br>30500-PTO-005<br>30500-PM3-005<br>30500-PM3-015<br><br>Civic 1.3/1.4<br>Accord 2.0<br>Concerto 1.4 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC02** | **Toyota**<br>90919-02163<br>**Isuzu**<br>8-94404-545-0<br>**GM**<br>94404545, 94853695<br><br>Camry 95-92, Corolla 97-95<br>Paseo 95-92, Tercel 97-874<br>Runner 97-96, MR2 95-92 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC03** | **Toyota**<br>90919-02164<br>**Isuzu**<br>8-9440, 4-545-0<br>**GM**<br>94404545, 94853695<br><br>Celica 95-94, Corolla<br>95-93, Corolla 89-86,<br>Tercel 87 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC04**<br>**PIC78** | **Daihatsu**<br>90048-52102<br>90048-52056<br>90048-52096<br><br>(S88) |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC05** | **Daihatsu**<br>90048-52094<br>(S89)<br>**Mitsubishi**<br>MD-309455<br>**Suzuki**<br>33410-50G10<br>33410-62E10 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC06** | **Daihatsu**<br>90048-52110<br><br>(S91) |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC07**<br>**PIC07(b)** | **Toyota**<br>90919-02239, 90080-19019<br>90080-19015, 90919-T2002<br>90919-02262<br>**GM**<br>94859442<br><br>Corolla 07-00, Celica 05-00<br>MR2 05-00, Matrix 07-03<br>Chevrolet Prizm 02-00<br>Pontiac Vibe 07-03 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC09** | **Honda**<br>30520-PVF-01<br>30520-PGK-A01<br>30520-PUK-A01<br><br>Acura MDX 06-01<br>Civic 04-01<br>Civic 05<br>Pilot 05-03<br>Ridgeline 08-06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC10** | **Nissan**<br>22448-4M500<br>22448-4M50A<br><br>Sentra 01-00 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC11**<br>**PIC395** | **Toyota**<br>90919-02240<br>90080-19021<br>90919-T2003<br>90919-02265<br><br>Echo '00-'05<br>Prius '06-'10<br>Scion xB 1.5L '04-'06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC12** | **Nissan**<br>22448-31U06<br>22448-31U16<br><br>Maxima/ Cefiro '95-'97<br>Infiniti I30 '96-'99 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC13**<br>**PIC99** | **Nissan**<br>22448-31U00<br>22448-31U01<br>22448-31U11<br><br>Maxima / Cefiro '95-'97<br>Infiniti '96-'99 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC14** | **Honda**<br>30520-REA-Z01<br>30520-PWA-003<br><br>Jazz, City, CRV<br>Civic '03-'05 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC15** | **Honda**<br>30521-PWA-003<br>30521-PWA-008<br><br>Jazz, City, CRV<br>Civic '03-'07 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC17** | **Hyundai**<br>27301-24000<br><br>Excel FBC |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC18**<br>**PIC36** | **Hyundai / Kia**<br>27301-26002<br>OK2A3-18-100A<br>OK247-18-100<br>OK247-18-100A<br><br>Avante 1.5 (old)<br>Kia Shuma 1.5i<br>Sephia II |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC19** | **Hyundai**<br>27301-26080<br>**GM**<br>88921377<br><br>Avante 1.5 (new) |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC20**<br>**PIC197** | **Hyundai**<br>27301-22040<br>27301-22050<br><br>Accent (X-3)<br>Accent Saloon (X-3)<br>1.3, 1.3i, 1.5i<br>Accent (X-3) 1.5i 12V<br>Lantra II (J-2) 1.5 12V |

MOQ: 50pcs

# IGNITION COILS



| Part No.: | Application: |
|---|---|
| **PIC21** | **Hyundai**<br>27301-35511<br><br>Granduer<br>2.5,3.0 DOHC |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC23** | **Hyundai**<br>27301-32800, 27301-32810<br>2301-32820<br>**Mitsubishi**<br>MD-104696<br>Sonata 2.4i SOHC 88-91<br>Sonata I 1.8i 88-93<br>Sonata I 2.0i 91-93<br>Galant VI 87-10<br>Space Wagon 2.0, 2.4<br>Galant III 2.4 GLS 85-87` |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC24** | **Hyundai / Kia**<br>27301-38020<br><br>Santa Fe 02-01<br>Sonata 04-99<br>Optima 05-01 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC31** | **Kia**<br>OK201-18-10XB<br>OK201-18-10XC<br><br>Sephia 1.5L '96-'98<br>Mits. Diamante '92-'96<br>Mits. 3000GT '97-'99 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC32**<br>**PIC196** | **Hyundai**<br>27301-22600<br><br>Accent |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC33** | **Kia**<br>OK013-18-100<br><br>Sportage 02-95 |

MOQ: 50pcs

*With Module -*
*4 Pins Connector*

| Part No.: | Application: |
|---|---|
| **PIC34** | **Daewoo / Opel / GM**<br>96350585, 380017,<br>1208051,1104047, 1104038,<br>10450424, 10490192,<br>8-01101-038-0,<br>8-01104-038-0<br><br>Leganza 2.2i 09-98<br>Lanos 1.3i 04-97<br>Tacuma 1.8i<br>Frontera 2.2i 09-98<br>Isuzu |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC36**<br>**PIC18** | **Hyundai / Kia**<br>27301-26002<br>OK2A3-18-100A<br>OK247-18-100<br>OK247-18-100A<br><br>Avante 1.5 (old)<br>Kia Shuma 1.5i<br>Sephia II |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC37** | **MItsubishi**<br>MD-361710<br>MD-344196<br>900700-048<br><br>Proton Waja<br>4G18 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC38** | **Hyundai**<br>27300-39700<br><br>Santa Fe (LPG) |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC39** | **Hyundai**<br>27301-23003<br><br>Tiburon,<br>Avante1.8<br>Elantra XD 1.6 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC44** | **VW**<br>330905 115A<br><br>**Bosch**<br>0221 502 007<br>0221502008<br><br>Santana 2000 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC45**<br><br>**PIC96** | **Mitsubishi**<br>MD131711, MD098964,<br>MD104696, MD166146,<br>MD113551, MD141004,<br>**Hyundai**<br>27301-35010<br>**Kia**<br>KK137-18-100, KK137-1810X<br>KK137-18-10XC<br>**Nissan**<br>22433-12P01, 22433-12P11<br>22433-V4410, 22448-03E01<br>22448-03E11 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC46** | **Alfa Romeo** 46410164<br>**GM**<br>1103905,1103872,10457075,<br>1103982,1104003,<br>**Fiat** 7778982,<br>**Marelli** 940038528,940038528010<br>**Opel** 1208063 Opel Astra 1.4i<br>**Motorcraft** D553<br>**Pontiac** Sunbird 92-93 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC48**<br><br>**PIC106** | **Suzuki**<br>33410-8500<br>33410-85100<br>33410-85120<br>33410-81430<br><br>**Diamond**<br>MIC-2000, GC-5<br>FTM-063GT<br>F-076 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC55** | **Toyota**<br>90919-02218<br>90919-02217<br>90919-02220<br>90080-19007<br>90080-19008<br><br>**Tacoma**<br>2WD14 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC56** | **Motorolla**<br>01R43059X01<br>101R42076X01 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC57** | **Honda**<br>30510-P73-A01<br>30510-P73-A02<br>30510-PT2-006<br><br>Accord 2000<br>19017118, E-545<br>Acura 92-98 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC58** | **Mitsubishi**<br>MD-155852<br>H3T024F-696<br>Eclipse 94-90<br><br>**Plymouth**<br>Laser 94-91<br><br>**Eagle**<br>Talon 94-93 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC60** | **Mazda / Ford**<br>19017116, 1 649 067, 6 503 279, 6 503 281,<br>F-510, 88F-12029-A1A, 8SF-12029-A1A,<br>88SF-12029-A2A, 928F-12029-CA, DG-435,<br>DG-449, DG-454, DG-457, DG-458, DG-460<br>DG-461, E8TF-12029-AA, EE-03A, E8TZ-12029-A,<br>E9TF-12029-AA, F1VU-12029-A1A,<br>F1VU-12029-A2A, F1VY-12029-A,<br>F5LU-12029-AA, F5LY-12029-A, F5OU-12029-AA<br>F5OY-12029-A, F5OY-12029-B, F5RZ-12029-C,<br>ZZM0-18-100, F37U-12029-AA, F37Z-12029-A<br>FSD7-18-100<br>Denso 029 700 6700<br>Ford 91-99 Ford 89-99<br>Mazda 94-97 Mercury 91-99 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC61** | **Ford**<br>1 075 786, 1 119 835,<br>1SG-12029AB<br>988F-12029-B<br>988F-12029-AC<br>1317972<br><br>**Mazda**<br>Y F09 18 10X<br><br>ME 85-02<br>Marshall 40512 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC66**<br>**PIC285** | **Chrysler**<br>5269670, 56032521,<br>5269670AB<br><br>Dodge '97-'01<br>Jeep<br>Cherokee 2.4L '09-'01<br>Wrangler 2.4L |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC67** | **Chrysler**<br>4557468, 5296670<br>4609080, 4671025<br><br>**Ford**<br>DGE443 DGE441<br>E8BZ-12029-A<br>E8BZ-12029-B<br>MO 4557468, MO 4777667<br>5269670<br>Neon 4671025<br>Dodge '95-'97<br>Plymouth '97 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC69** | **Toyota**<br>19070-74170<br>19500-74090*U<br>19500-74100*U<br>90919-02209<br>90919-02207<br>19080-46020<br><br>Lexus 92-97 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC71** | **Mitsubishi**<br>MD339027<br><br>**Diamond**<br>F-809<br><br>Mitsubishi 4G64 - 98<br>Delica |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC72** | **Mitsubishi**<br>MD338169<br><br>**Freeca**<br><br>DN6440\703\71DLK/FLK |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC74**<br>**PIC83** | **Daewoo / GM/ Opel**<br>96350585, 10450424,<br>1104038, 1104047,<br>10490192, 19005241,<br>1104047, 1208051,<br>8-01101-038-0, DQG1210<br>3705010A6,<br><br>Astra G Box (F70)1.6L '00-05<br>Combo Tour 1.6L '01- |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC76** | **Ford**<br>6V87QE-3705010A<br>6V87QE-3705010B<br>DQG691, DQG691A,<br>DQG691SA |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC77** | **Daihatsu**<br>029700-6020<br><br>Auto K26 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC04**<br>**PIC78** | **Daihatsu**<br>90048-52102<br>90048-52056<br>90048-52096<br><br>(S88)<br>**Diamond**<br>F-076, F-614<br><br>S/X1.0 87-90<br>CX1.3, 16V 88-90 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC79**<br>**PIC188** | **Marelli**<br>060780002010,<br>060708038010,<br>**Fiat**<br>7672018, 7626232,<br>46543562<br>**Alfa Romeo**<br>46548037, 60805420,<br>60809492<br>Bosch F0002S0103<br>Lucas DLB 314 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC80** | **Peugeot / Citroen**<br>597045, 9603528480<br>**Magneti Marelli**<br>06705738010, 06705754010<br><br>**Citreon**<br>AX 1.0L, 1.1L, 1.3L, 1.4L 91ZX<br>1.1L, 1.4L 91<br>**Peugeot**<br>106 1.0 1.1 1.1i 1.4 1.4i 91<br>205 1.0 1.1 90<br>606 2.0 90-91 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC81** | **Motorola**<br>01R4304R01<br><br>**Nissan**<br>Tiida, Tenan, Sylphy<br>Geniss, Livina, Paladin,<br>X-trail Cefiro, Fuga,<br>Cima, 350z<br>Marshall<br>ME 85-01 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC82** | **Peugeot / Citroen**<br>597048, 597060, 96074054<br>**Fiat**<br>9607495480, 9607405482,<br>9622889780<br><br>Xsara '97 - '00<br>Ducato Box '88 - '90<br>106 Mk II '97 - '01 |

MOQ: 50pcs

| Part No.: | Applicatio |
|---|---|
| **PIC84** | **VW**<br>032 905 106, 032 905 106 B,<br>032 905 106D, 0221 603006<br>0221 603010<br><br>Golf 1.4i 2000<br>Lupo 1.4i 2000<br>Passat 2.0i 2000<br>Polo 1.4i 99<br>Seat, Skoda |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC85** | **Jeep / Chrysler**<br>4751253, 4797293,<br>5234210, 5252577<br>C506 19017110<br><br>Cherokee '91-'97<br>Dodge '90-'95<br>Jeep '90-'97<br>Plymouth '91-'95 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC86** | **VW**<br>867 905 104, 867 905 105A<br>357905104, 547905104<br>7019505104, 70195104A<br>867905104A, 867905352<br>**Bosch**<br>0221601006, 0221601007,<br>0221601001, 0221601002<br><br>VW 92-97<br>Skoda 004050016 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC87** | **Audi / VW**<br>6N0905104, 6N0905104A<br>867905104A, 867905352,<br>54795104<br><br>Skoda 004050016<br><br>Bosch<br>1227022030<br>1227030030 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC88** | **GM**<br>D539, D540, D555,<br>1103608, 1103646,<br>1103662, 1103663,<br>1103744, 1103745,<br>1103746, 10468391,<br>10472401, 10497771<br>10495121<br>Oldsmobile 3.3L V6<br>Pontiac Grand Prix 3.8L V6 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC90**<br><br>**PIC104** | **Nissan**<br>22433-03G01, 22433-10G10<br>22433-03G11, 22448-03G01<br>22448-03G11, 22488-04G01<br>22448-04G11, 22448-10G00<br>22448-11G00, 22448-19B10<br>22448-29R10, 22448-32F11 F<br><br>Stanza 2.0L '89<br>Micra 1.2L ' 88<br>D21 3.0L '87<br>200SX 3.0L '87<br>Pathfinder 3.0L '87 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC91** | **Daihatsu**<br>19080-Z9121<br>19080-87703<br>100297-0860<br><br>**Mitsubishi**<br>MD-339027 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC92** | **Citroen/ Alfa Romeo**<br>597053, 76487970<br>**VW**<br>048 905 105 1<br>**Ferrari**<br>134386<br>**Honda**<br>30520-PDF-E00<br>**Land Rover**<br>ERR6045, ERR6566<br>**Renault** 6000581617 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC95** | **Audi / VW**<br>032 905 106, 032 905 106 B<br>032 905 103B<br><br>Audi A3 1.8i 20v<br>A4 1.6i 20v 96<br>VW A4 16i/2.0i 99<br>VW Bora 1.6i 991.4i 2000<br>Lupo 1.4i 2000<br>New Beetle 2.0i 98<br>Passat 2.0i 2000<br>Polo 1.4i 99 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC96**<br><br>**PIC45** | **Daewoo / Nissan**<br>96320818, 96336522,<br>19017022, 22433-12P00,<br>22433-12P01, 22433-12P10,<br>22433-12P11, 22448-89R10,<br>22448-61A00, 22448-61A10,<br>22448-89W00, 22448-89W10,<br>22448-90W00, 22448-90W10<br>**Hitachi** CM1T-205<br>**Hyundai** 27301-35010<br>**Kia** 137-18-10XC |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC97**<br><br>**PIC249** | **Mazda**<br>FFY1-18-100<br>FP85-18-100C<br><br>323 2.0L '98-'04,<br>Protege 5 2.0L '02-'03<br>Premacy 2.0L '01-'05<br>Tierra 2.0L |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC99**<br>**PIC13** | **Nissan**<br>22448-31U00<br>22448-31U01<br>22448-31U10<br>22448-31U11<br><br>Maxima 99-95<br>Infiniti I30 97-96 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC101**<br>**PIC299** | **Nissan**<br>22448-8H300<br>22448-8H315<br>22448-8H310<br>22448-8H311<br><br>Altima 06-02<br>Sentra 06-02 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC104**<br>**PIC90** | **Nissan**<br>22433-03G01, 22433-03G10<br>22433-03G11, 22433-10G10<br>22448-19B10, 22448-03G01<br>22448-03G11, 22448-04G01<br>22448-D4503, 22448-04G11<br>22448-10G00, 22448-10G10<br>22448-D4510, 22448-11G00<br>22448-11G10, 22448-29R10<br>22448-D4501, 22448-D4505<br>22448-D4506, 22448-D4511<br>22448-D4512, 22448-D4513<br>22448-D4515, 22448-D4516 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC106**<br>**PIC48** | **Suzuki**<br>33410-8500<br>33410-85100<br>33410-85120<br>33410-81430<br><br>**Diamond**<br>MIC-2000, GC-5<br>FTM-063GT<br>F-076 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC107** | **Peugeot**<br>33002299, 7701031135,<br>12336238, U-504,<br>80 5034 3287677-3<br>**Chryster** T1031135<br>**Marelli** Bae 504 B<br>**Volvo** 3287677-3<br><br>**Eagle** 88-92<br>**Jeep** 86-90<br>**Volvo** 82-89 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC108** | **Renault**<br>7700875000, 7700107177<br>7700113357, 0040100052<br>8200208611, 8200568671<br>029700-8291<br><br>**Nissan**<br>2448-00QAE<br><br>Renault Clio 2L '02-'06<br>Renault Scenic '02<br>Nissan Platina 1.6L '02-'06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC109** | **GM / Opel**<br>1208003, 1208054<br>1208070, 90449739<br>90510386, 905103086,<br><br>Opel Omega '86-'94<br>Vauxhall Carlton '86-'94<br>Opel Vectra '88-'03<br>Opel Combo '94-'01 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC113** | **Nissan**<br>22433-OM200<br>22433-F4302<br><br>**Toyota**<br>90919-02200<br><br>CM1T227<br><br>X-Terra 2.4L '00-'03<br>PickUp 2.4L '96-'97<br>Sentra 1.6L '95-'99 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC115**<br>**PIC122** | **GM / Ford**<br>D-523, D-530, D-532,<br>8131936, J8131936, 1875894,<br>1985473,10497132,<br>C0NP-12029-A,<br>DGG-419,1694925-C1, 5-71<br><br>(Wires-Red and Yellow)<br><br>GMC C1500 L6-4.1L '79<br>Cadillac Seville V8-4.1L '82<br>Pontiac Sunbird L4-2.5L '77-'80<br>Chevrolet R3500 V8-7.4L '89 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC118** | **Ford**<br>E1EF-12029-AA,12321405,<br>12336833, 19017194,<br>F-503, FD478, F-1953,<br>DG-325, DG-325A,<br>DG-325ADP,<br>DG-434, DGE-453,<br>ZZM1-18-100,<br>ZZM4-18-100,<br><br>Ford '82-'97, Ford Truck '83-'97,<br>Lincoln '84-'94, Mercury '82-'95,<br>Mazda '94-'97 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC123** | Universal coil for<br>six cylinder direct<br>ignition gasoline<br>engine |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC124** | **Peugeot**<br>597047605 2.0 90-91<br>**Citroen** 96041378<br>**Fiat** 9604137880<br>**Valeo**<br>245038, CD326<br>2526024, 2526024A<br><br>**Citroen** XM 2.0L 89 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC126** | **Citroen / Peugeot**<br>97531206, 597042, 597046<br><br>**Marelli**<br>Bae 507 AK, 60705701,<br>060705738010, 60705738<br><br>Citroen C15 '84-'96<br>Citroen ZX '91-'97<br>Citroen BX '82-'94<br>Peugeot Partner '96<br>Peugeot 309 '87-'93 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC127**<br><br>**PIC277** | **Fiat**<br>7582152, 7663177,<br>7698431, 7746152, 7746154<br>**Marelli**<br>Bae 506, Bae 506D,<br>060705604010, 60705604<br><br>Fiat Tipo '89-'95<br>Lancia Y10 '85-'89<br>Fiat Tempra '92-'96<br>Fiat Uno '89-'92<br>Fiat Panda '85-'92 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC129** | **Mitsubishi**<br>MD619849<br><br>H3T023<br><br>Diamond F-695<br><br>Chrysler Sebring 2.5 V6<br>'95-'00<br>Dodge Avenger 2.5 V6<br>'95-'00<br>Chrysler Cirrus 2.5 V6<br>'95-'00 |

MOQ: 50pcs

*With Module -*
*3 Pins Connector*

| Part No.: | Application: |
|---|---|
| **PIC130** | **Daewoo**<br>96253555, 93363483,<br>93363486, 19005265,<br>19005236<br>**Suzuki**<br>33410-84Z00<br><br>Chevrolet Aveo 5 '03 - '12<br>Daewoo Nubira '00 - '02<br>Chevrolet Aveo '04-'13<br>Suzuki Forenza '04-'08<br>Suzuki Reno '05 - '08 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC133**<br><br>**PIC190** | **Lada**<br>2112-3705010-04<br>2112-3705010-07<br>2112-3705011-02<br>**TY**<br>42182 56003 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC135**<br><br>**PIC229** | **Toyota**<br>90919-02135, 90919-02136<br>90919-02139, 90919-02152<br>90919-02196<br>**GM**<br>94840127, 94847392<br>19017139, 94856381<br>**Suzuki**<br>94840127<br><br>Celica L4 1.6L '90-'93<br><br>Tercel L4 1.5L '90 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC136** | **Suzuki**<br>33410-77E01<br>33400-65G00<br>9C19-0370<br><br>Jimmy 1.3 '00-<br>Ingis 1.3 '00-<br>Swift 1.3, 1.5 '00-<br>Baleno 1.6 '96-<br>Holden Cruze YG 1.5 '02- |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC136A** | **Suzuki**<br>33400-65G00<br>33400-65G01<br>33410-77E01<br><br>Jimmy 1.3 '00-<br>Ingis 1.3 '00-<br>Swift 1.3, 1.5 '00-<br>Baleno 1.6 '96-<br>Holden Cruze YG 1.5 '02- |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC137** | **Citroen / Peugeot**<br>597045, 96010513,<br>97530780, 0986221029<br><br>AX 1.0L,1.1L,1.3L,1.4L<br>BX 1.1L,1.4L 83<br>205 1.1,1.4,1.6i,1.9i<br>309 1.1,1.4,1.6i 87<br>405 1.4,1.9i 87- |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC147** | **Toyota**<br>90919-02208<br>90919-02197<br>19500-74050<br>19080-50010<br>19080-50011<br><br>Celica '90-'93 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC148** | **Audi / VW**<br>377905105D<br><br>Bosch<br>9220081504<br>F000ZS0105<br><br>Pointer L4-1.8L '94-'98<br>Pointer L4-2.0L '00-'03<br>Pointer Truck L4-1.8L<br>'94-'99 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC150** | **Ford**<br>F5SZ-12029-A<br>E9SF-12029-AA<br>F1SU-12029-AA<br>F5SU-12029-A<br>F5SU-12029-AB<br>6489415, 6630365<br>6958305, 19017114<br><br>Contour '95 - '00<br>Ranger '98 - '00<br>Mazda B3000 '97 - '00 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC151** | **Dodge**<br>53006565, 5603250<br>560298AA, 88921268<br>56032520AB, 56032520AC<br>56032520AE, 56032520AF<br>**VW** 7B0905115<br><br>Chrysler Voyager V6 3.3L<br>'01-'03<br>VW Routan V6 3.8L<br>'09-'10 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC152** | **Audi / VW**<br>032905106B, 032905106D<br>032905106E, 06B905106D<br>0221603009, F000ZS0210<br>F000ZS1187<br><br>Audi A3 1.8 Quattro '98-<br>Audi A4 Avant 1.6 '94-'01<br>VW Golf IV 2.0 '02-'06<br>VW Passat 2.0 '90-'97 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC153**<br>**PIC273** | **Renault / Nissan**<br>7700875000<br>7700107177<br>0986221001<br>22448-00QAA<br><br>Renault Trafic '01<br>Laguna '93-'01<br>Espace '96-'05<br>Nissan Kubistar '03 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC154** | **Hyundai**<br>27301-02600, 27301-02620<br>27301-02630, 27310-22610<br>27301-38200<br><br>Atos Prime 1.1L '03-<br>Atos 1.0i G4HC '98-'03<br>Amica 1.0L '00-'03<br>Accent 1.5L '00-'03 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC155** | **Ford**<br>F7TU-12029-BA<br>F7TZ-12A336-BA<br>F7TU-12A366-AB<br>F7TU-12A366-CB<br>F7TU-12A366-CD<br>11202908, 88921369<br>1L2U-12029-AA<br>1L2U-12A366-AA<br>1L2Z-12029-AC |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC157** | **Audi**<br>078905104/A<br><br>A4（B6）2.4L |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC158** | **Suzuki**<br>3705010A4 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC159** | **Daihatsu**<br>90048-52109<br><br>Diamond F-714 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC163** | **Ford / VW / Mazda**<br>12029AA, 574905105B<br>7053859, 060801004010<br>95WF-12029-BA<br><br>Ford Escort<br>VW Golf '94-'08<br>VW Pointer '94-'08 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC164**<br><br>**PIC279** | **Peugeot / Citroen**<br>596319, 5970A9,<br>597072, 597074<br>96246755, 96281585,<br>9628 158580<br><br>Peugeot 306 1.4 '98-'00<br>Peugeot 106 1.4 '98-<br>Citroen Saxo 1.6 '98-'00<br>Citroen Xsara 1.6 '98-'00 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC165** | **Peugeot / Citroen**<br>597078, 597079,<br>597097, 5970A8,<br>96358649, 9635884880<br>9635864980<br><br>Citroen C15 '88-'96<br>Citroen BX '88-'92<br>Peugeot 306 '93-'02<br>Peugeot 307 '00-'03 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC166**<br><br>**PIC348** | **Lada**<br>2111-3705010<br>2111-3705010-03<br>F000 ZS0 211<br>Bosch 0221 504 461 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC170** | **Audi / VW**<br>701905104, 701905104A<br>867905104, 867905105A<br>867905352, 357905104<br>6N0905104, 0221601001<br>0221601002, 0986221002<br><br>VW Golf L4 2.0L '99<br>VW Cabrio L4 2.0L '99-02'<br>VW Jetta L4 2.0L '99 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC175** | **Renault / Nissan**<br>7700274008<br>7700875701<br>6001543604<br>22448-00QAC<br><br>Renault Megane '96-'03<br>Renault Twingo '96-'11<br>Nissan Kubistar '03-'06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC176**<br>**PIC258** | **Toyota**<br>19500-B0010<br>90048-52130<br><br>Avanza '02<br>Daihatsu Xenia '02 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC177** | **Toyota**<br>90919-02213<br><br>Denso<br>029700-7941<br>029700-7942<br>GM 88921357<br><br>Paseo 1.5L '96-'98<br>Tercel 1.5L '95-'98 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC178** | **Toyota**<br>90919-02212<br>Denso<br>029700-7951<br>029700-7952<br>GM 88921336, 88921337<br>Toyota T100 3.4 '95-'98<br>Tacoma 3.4 '95-'04<br>4Runner 3.4 '96-'02<br>Tundra 3.4 '00-'04 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC185** | **Mitsubishi**<br>MD363552<br><br>Savrin 2.0L 4G63 '01-'04<br>Eclipse II 2.0L '95-'99<br>Lancer 2.0L 4G63 '03-<br>Outlander I 2.0T L4 4G63T<br>'04-'06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC186**<br>**PIC420** | **Mazda**<br>ZZY1-18-10<br>ZL01-18-100<br>ZL01-18-100A<br>JJY1-18-100<br><br>323 1.5L '98-'01<br>MX-5 1.8L '01-'05<br>323 1.6L '01-'04<br>Miata 1.8L '01-'05 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC188**<br>**PIC79** | **Marelli**<br>060780002010<br>060708038010,<br>**Fiat**<br>46543562, 46790073<br>76262320, 7672018<br>7692473<br>**Citroen**<br>96062288, 9616597080 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC189** | **GM / Opel**<br>90458250, 1208071<br><br>Peugeot 205 Mk II '97-'98<br>Peugeot 306 '94-'95<br>Rover 400 '95-'00<br>Citroen AX '87-'98 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC190**<br>**PIC133** | **Lada**<br>2112-3705010-04<br>2112-3705010-07<br>2112-3705011-02<br>**TY**<br>42182 56003 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC191** | **Ford**<br>19017113, 22M7-18-100<br>6630365, 90TF-12029-A1A<br>6383157, ZZL0-18-100<br>6958305, KLG4-18-100A<br>F3DZ-12029A,<br>**Mazda**<br>ZZM7-18-100<br>DG-445, DG-459<br>DGE-446, DG-438 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC193** | **Mercedes Benz**<br>0001500280<br>0001587503<br>0001587103<br>**Daewoo**<br>1621500000<br>1621580001<br>**Audi / VW**<br>00A905105 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC32**<br>**PIC196** | **Hyundai**<br>27301-22600<br><br>Atos 1.3L G4EA '03-'08<br>Accent II 1.3L G4EA<br>'00-'05<br>Getz 1.3i G4EA '02-'04 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC197**<br>**PIC20** | **Hyundai**<br>27301-22040<br>27301-22050<br><br>Accent (X-3)<br>Accent Saloon (X-3)<br>1.3, 1.3i, 1.5i<br>Accent (X-3) 1.5i 12V<br>Elantra II (J-2) 1.5 12V |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC198**<br>**PIC203** | **Hyundai / Kia**<br>27301-23700<br>27301-23710<br><br>Elantra '03-'06<br>Tiburon '03-'08<br>Tucson '05-'07<br>Sportage '05-'07 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC202** | **Hyundai / Kia**<br>27301-37100<br>27301-37105<br>UF284, UF-337<br><br>Sonata '99-'05<br>Magentis '01-'06<br>Optima '01-'06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC204** | **Hyundai**<br>27301-02502 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC206** | **Kia**<br>OK011-18-100<br>**Land Rover**<br>ERR6045, ERR6566<br>**Fiat / Alfa Romeo**<br>76487970, 7648797<br>60558152, 60809606<br>**Honda**<br>30520-PDF-E00<br>**Ferrari**<br>134386 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC207** | **Ford**<br>1F2Z-12029-AC<br>1F2U-12029-AC<br>919F-12029-AA<br>E9SF-12029-AA<br>F1SU-12029-AA<br><br>Freestar '04<br>Taurus SEL '04<br>F-150 4.2 V6 '05<br>Mustang 3.8 V6 '04 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC208** | **Opel / Chevrolet**<br>55573735, 55575499<br>55577898, 55579072<br>1208092, 1208093<br>1208096, UF-669<br><br>Insignia '11-<br>Astra '03-'12<br>Cruze '11-'14<br>Sonic '12-'14 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC209**<br><br>**PIC328** | **Honda**<br>30500-P2A-J01<br>**Hitachi**<br>CM1T-230, CM1T-230A<br>CM1T-231, CM1T-231S<br><br>Infiniti QX4 3.3L V6<br>Frontier 3.3L V6<br>Pathfinder 3.3L V6 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC210** | **Mitsubishi**<br>H3T-03471<br>**Proton**<br>IGC-098<br>**Diamond**<br>F-761 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC211** | **Audi / VW**<br>06B905115E<br><br>A3/ A6/ A8 TT<br>Passat 1.8 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC212** | **Jaguar / Ford**<br>XW4U-12A366-AC<br>XW4Z-12029-AA<br>2W4Z-12029-AC<br>2W4E-12A366-AC<br>2W4E-12A366-AD<br>5008049<br><br>Lincoln LS V6 3.0L<br>'00-'05<br>Jaguar S-Type V6 3.0L<br>'00-'04 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC213** | **Jaguar / Ford**<br>1W4U-12A366-BA<br>1W4Z-12029-BA<br>2W4Z-12029-BD<br>2W4E-12A366-BB<br>2W4E-12A366-BC<br>2W4E-12A366-BD<br>4W4Z-12029-BA<br>FD506<br><br>Lincoln LS 3.9L V8 '02-'05<br>Jaguar S-Type 4.0L V8<br>'00-'03 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC214** | **Mercedes Benz**<br>029700-8040<br>88921407<br><br>**Jaguar**<br>LCA1510AB<br><br>Jaguar XJR '98<br>Jaguar XK8 V8-4.0L '97-'99 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC215**<br><br>**PIC388** | **Toyota**<br>90919-02215<br>90080-19012<br><br>Lexus ES '91-'08<br>Kluger '00-'07<br>Avalon '96-'99<br>Camry '91-'08<br>Harrier '98-'08<br>Alphard '03-'08 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC217** | **Nissan**<br>22448-2Y005<br>22448-2Y006<br>**Mitsubishi**<br>H6T10271A<br>**Hitachi**<br>IGC0024<br><br>Infiniti I30 V6 3.0<br>Maxima V6 3.0<br>'00 - '01 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC221** | **Kia**<br>0K011-18-100<br>**Fiat / Alfa Romeo**<br>60809606, 76487970<br>**Citroen / Peugeot**<br>597053, 0221503407<br>**Honda**<br>30520-PDF-E00<br><br>KIA Sportage L4-2.0L<br>'94-'04 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC222** | **Mazda**<br>L813-18-100<br><br>Mazda 6 1.8 / 2.0 / 2.3L<br>'02-'07<br>Mazda MPV 2.3L '03-'06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC227** | **Audi / VW**<br>06A 905 104<br>06A 905 097<br>0986221049<br><br>Bora 2.0 APK '98-'05<br>New Beetle 2.0 AEG<br>'98-'10<br>VW Caddy III Box '06-<br>Santana 3000<br>Octavia 2.0L '99-'07 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC228**<br>**PIC238** | **Renault**<br>77 00 863 021<br>77 00 854 306<br>77 00 872 265<br>**Marelli**<br>60708138, BAE801AK<br><br>Espace '93-'01<br>Renault 21 '90-'92<br>Megane '96-'03 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC229**<br>**PIC135** | **Toyota**<br>90919-02135, 90919-02136<br>90919-02139, 90919-02152<br>90919-02196<br>**GM**<br>94840127, 94847392<br>19017139, 94856381<br>**Suzuki**<br>94840127<br>Celica L4 1.6L '90-'93<br>Tercel L4 1.5L '90 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC239** | **Renault**<br>77 00 854 307<br>77 00 872 692<br><br>**Marelli**<br>BAE 801 BK<br><br>Laguna '93-'01<br>Renault 21 '90-'92<br>Espace '96-'98 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC240** | **Renault**<br>77 00 858 320<br>77 00 872 693<br><br>**Marelli**<br>BAE 801 CK<br><br>Laguna '93-'01<br>Grandtour Z7X 765<br>'96-'01 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC242**<br>**PIC346** | **Mazda**<br>B6S7-18-100, B6S7-18-10XA<br>B6S8-10-10XA, B6S8-18-10XA<br>F269-18-10X, F269T18-10X<br>**Ford**<br>F0BZ-12029-A<br>F0C6-12029-AA<br>F1CZ-12029-A<br><br>Mazda Protege 1.8L '94<br>Mazda B2200 2.2L '93<br>Ford Escort 1.8L '92 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC245** | **Opel**<br>1208065, 90449572<br>**GM**<br>90443900<br>0221503001<br><br>Frontera '95-'98<br>Opel Vectra '89-'95<br>Vauxhall Astra '88-'98<br>Vauxhall Calibra '90-'97<br>Vauxhall Cavalier '86-'95 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC247** | **Toyota**<br>90919-02243, 90919-02244<br>90919-02266, 90919-19023<br>90080-19023, 099700-0683<br>099700-0910, 099700-1920<br><br>Camry L4 2.4L '02-'05<br>RAV4 L4 2.4L '04-'08<br>Camry Hybrid L4 2.4L '07-'08<br>Lexus HS250h L4 2.4L '10-'12 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC248**<br>**PIC400** | **Honda**<br>30520-PMA-007<br>30520-PNA-007<br>30520-PRA-007<br>30520-PWA-007<br>30520-RAA-007<br>30520-RRA-007<br><br>Accord 2.4 L4 '03-'05<br>Civic '02-'05<br>CR-V '02-'06<br>Acura RSX '02-'06 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC249**<br>**PIC97** | **Mazda**<br>FFY1-18-100<br>FP85-18-100C<br><br>323 2.0L '98-'04,<br>Protege 5 2.0L '02-'03<br>Premacy 2.0L '01-'05<br>Tierra 2.0L |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC255** | **Renault**<br>8200 360 911<br>8200 702 693<br>0986221046<br><br>Kangoo '01-<br>Modus '04-'08<br>Thalia '02-'08<br>Twingo '04-<br>Clio '01-'13 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC256** | **Opel**<br>1208008<br>90536194<br>9119567<br><br>Astra '98-'05<br>Corsa '00-'09<br>Meriva '03-'10<br>Vectra '95-'06<br>Vauxhall Meriva '03-'05<br>Saab 9-3 '04-'05 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC257** | **Toyota / Daihatsu**<br>90048-52125<br>90048-52126<br>099700-0570<br>099700-02510<br><br>Toyota Duet '98-'04<br>Daihatsu Materia '06<br>Daihatsu Coo '06<br>Daihatsu Xenia '02-'07<br>Daihatsu Move '98 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC258**<br>**PIC176** | **Toyota**<br>19500-B0010<br>90048-52130<br><br>Avanza '02<br>Daihatsu Xenia '02 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC259**<br>**PIC396** | **Toyota**<br>90919-T2001, 90919-T2005<br>90919-T2008, 90919-A2001<br>90919-A2006, 90919-C2002<br>90919-C2006, 90919-02247<br>90919-02248, 90919-02260<br><br>Scion TC '05-'10<br>FJ Cruiser '07-'09<br>Tacoma 2.7 '05-'10<br>Camry 2.4 '07-'09 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC260** | **Suzuki**<br>33400-62J00<br>33400-83E10<br>33410-66D00<br>33410-66D01<br><br>Alto '98-'00<br>Swift '89-'05<br>Grand Vitara '98-'03<br>Wagon '01-'03<br>Baleno '95-'02 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC261**<br>**PIC312** | **Toyota/ Daihatsu**<br>19070-BZ040<br>JK099700-0990<br>20181-CE121<br><br>Avanza 3SZ '06-<br>Liteace '08-<br>Perodua Myvi |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC262** | **Hyundai / Kia**<br>27301-3E100<br>UF554<br><br>Tiburon '06<br>Santa FE '00-'07<br>KIA Opirus '06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC263** | **Mitsubishi**<br>MD-362907<br>MD-325048<br>88921386<br>89057964<br>UF-295, 4G64, 4G93<br><br>Lancer 2.0L '02-'07<br>Carisma 1.8L '95-'06<br>Pajero Sport 1.8L '99-'05<br>Colt IV 1.8L '92-'96 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC264** | **Hyundai / Kia**<br>5WY2407A<br><br>Pride / Rio |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC265** | **Toyota**<br>90919-02217<br>90919-02218<br>90919-02220<br>90080-19007<br>90080-19008<br><br>Camry 2.2L '97-'01<br>Solara 2.2L '99-'01<br>RAV4 2.0L '98-'00 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC266** | **Chrysler / Jeep**<br>56028138<br>56028138AB<br>56028138AD 56028138AE<br>56028138AF 56028138BA<br><br>Durango 4.7L V8 '00-'07<br>Commander 3.7L V6 '06-'07<br>Dakota 4.7L V8 '00-'07<br>Grand Cherokee 3.7L V6 '05-'07 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC268** | **Opel**<br>1208012<br>0221503015<br>90543253<br><br>Astra G 1.2 16V '98-<br>Corsa B 1.2 16V '98-<br>Corsa C 1.2 16V '98- |

MOQ: 50pcs



*Black Plug*

| Part No.: | Application: |
|---|---|
| **PIC269** | **Peugeot / Citroen**<br>597056<br>96213086<br><br>Peugeot 307 1.6L '02-<br>Peugeot 106 1.6L '98-'09<br>Citroen SEXO 1.6VTS |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC270** | **Ford**<br>EF-12029-A<br>94DA-12029AC<br>9220061800<br><br>Fairlane 4.0L '98-'00<br>Fairlane 4.0L '94-'96<br>Falcon 4.0L '95-'96 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC271** | **Ford / Mazda**<br>1L8Z-12029-AA<br>1L8Z-12029-AB<br>1R8E-12A366-AC<br>1L8E-12A366-AC<br>9L8E-12A366-AA<br>XS2U-12A366-AA<br>DG-539, FD502<br><br>Escape V6 3.0L '01-'08<br>Taurus V6 3.0L '04-'99<br>Tribute V6 3.0L '01-'03 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC272** | **Ford**<br>1F3Z-12029-AA /AC<br>1F3U-12A366-AA<br>2C6U-12A366-AA /AC<br>4L7Z-12029-AA<br>4L7E-12A366-AA /AB<br>DG-512<br><br>Mustang 5.4L V8 '07-'11<br>GT 5.4L V8 '05-'06<br>Lincoln Mark VIII 4.6L V8 '97-'98 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC273**<br>**PIC153** | **Renault / Nissan**<br>7700875000<br>7700107177<br>0986221001<br>22448-00QAA<br><br>Renault Trafic '01<br>Laguna '93-'01<br>Espace '96-'05<br>Nissan Kubistar '03 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC274** | **Lada**<br>2112-3705010-10<br>2112-3705010-13<br>050203050<br>350023250<br>1220703202<br>0221504461 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC275** | **Dodge**<br>56032521<br>56032521AB |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC277**<br>**PIC127** | **Fiat**<br>7582152, 7663177,<br>7698431, 7746152, 7746154<br>**Marelli**<br>Bae 506, Bae 506D,<br>060705604010, 60705604<br><br>Fiat Tipo '89-'95<br>Lancia Y10 '85-'89<br>Fiat Tempra '92-'96<br>Fiat Uno '89-'92<br>Fiat Panda '85-'92 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC278** | **GM / Opel**<br>61208007, 90511450<br>90492255, 0221503010<br><br>Vectra B '98-'00<br>Omega B '94-'00 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC279**<br>**PIC164** | **Peugeot / Citroen**<br>596319, 5970A9,<br>597072, 597074<br>96246755, 96281585,<br>9628 158580<br><br>Peugeot 306 1.4 '98-'00<br>Peugeot 106 1.4 '98-<br>Citroen Saxo 1.6 '98-'00<br>Citroen Xsara 1.6 '98-'00 |

MOQ: 50pcs

# IGNITION COILS

*Gray Plug*

| *Part No.:* | *Application:* |
|---|---|
| **PIC280** | **Peugeot / Citroen**<br>597080, 597099<br>2526182A, 96363378<br><br>Peugeot 307 1.6L '00-'05<br>Peugeot 206 1.6L '98-'09<br>Citroen C2/C3 1.6L '02-'03<br>Citroen C4 1.6L '05<br>Citroen Xsara '01-'05 |

MOQ: 50pcs

| *Part No.:* | *Application:* |
|---|---|
| **PIC281** | **Daewoo**<br>LF479Q1-3705100A<br>DA462-1AD<br>19005270<br>19005338<br>9015239 |

MOQ: 50pcs

| *Part No.:* | *Application:* |
|---|---|
| **PIC282** | **BMW**<br>121317 03359<br>121390 66468<br>121317 26177<br>121317 31884<br><br>320i M50 B20 '90-'00<br>530i M60 B30 '92-'97<br>M3 S50 B30 '94-'95<br>Z3 M52 B20 '99-'03<br>740i, iL M60 B40 '92-'01 |

MOQ: 50pcs

| *Part No.:* | *Application:* |
|---|---|
| **PIC283** | **Nissan**<br>22448-2Y000<br>22448-2Y001<br>22448-2Y010<br><br>Maxima '00-'01<br>Infiniti I30 '00-'01 |

MOQ: 50pcs

*3-pins*

| *Part No.:* | *Application:* |
|---|---|
| **PIC284** | **Suzuki**<br>33410-77E20<br>33410-77E21<br>33410-77E22<br>H006T14171A<br>H006T14171B<br><br>Grand Vitara V6 2.7L '01<br>Aerio L4 2.0L '02-'03 |

MOQ: 50pcs

| *Part No.:* | *Application:* |
|---|---|
| **PIC285**<br><br>**PIC66** | **Chrysler**<br>5269670, 56032521,<br>5269670AB<br><br>Dodge '97-'01<br>Jeep<br>Cherokee 2.4L '09-'01<br>Wrangler 2.4L |

MOQ: 50pcs

| *Part No.:* | *Application:* |
|---|---|
| **PIC286** | **VW**<br>036 905 100A<br>036 905 100B<br>036 905 100C<br>036 905 100D<br>036 905 100E<br><br>Golf VI 1.4 TSI '08-'12<br>Polo 1.4 '01-'07<br>Beetle 1.4 TSI '11-<br>Jetta I 1.6 FSI '06-'08 |

MOQ: 50pcs

| *Part No.:* | *Application:* |
|---|---|
| **PIC287** | **Nissan**<br>22433-60U02<br>22448-02U11<br><br>Skyline |

MOQ: 50pcs

| *Part No.:* | *Application:* |
|---|---|
| **PIC288** | **Eldor**<br>78300001<br><br>**Chery**<br>BD-0074445A<br>S11-3705110EA<br><br>Chery QQ 0.8 |

MOQ: 50pcs

# IGNITION COILS

2-pins

| Part No.: | Application: |
|---|---|
| **PIC289** | **Suzuki**<br>33410-77E1<br>33410-77E10<br>33410-77E11<br>88921356<br><br>SX4 '06-'10<br>Sidekick 1.8L '97-'96<br>Grand Vitara '96-'05 |

MOQ: 50pcs

6-pins

| Part No.: | Application: |
|---|---|
| **PIC290** | **GM / Opel**<br>1208307<br>19005212<br>0986221039<br><br>Astra G 1.4/1.6 16V '98-<br>Corsa C 1.4 '00-<br>Vectra B 1.6 16V '95-'02<br>Stilo 1.8 16V |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC291**<br><br>**PIC322** | **Chery**<br>A11-3705110EA<br><br>0221 503 465 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC292** | **GM**<br>D-548<br>1106013<br>1115315<br>10477944 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC295** | **Hyundai / Kia**<br>27300-39800<br>27300-39A00<br><br>Santa FE '00-'06<br>Terracan '01-'06<br>Carnival '02-'06<br>Magentis '05<br>Sorento '02-'06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC297** | **VW**<br>021 905 106<br>021 905 106A<br>95VW-12029-AA<br>95VW12029AA;<br>31088001<br>**Mercedes Benz**<br>0031585001<br><br>EuroVan 2.8L '97-'01<br>Passat 2.8L '95-'97 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC298** | **Audi / VW**<br>058905101<br>058905105<br>0986221011<br>0040100016<br><br>A6 2.7 T Quattro '97-'05<br>TT 1.8 T Quattro '98-'06<br>A3 1.8 T Quattro '98-'03<br>A6 Avant 1.8 '98-'05<br>VW Bora 1.8 '00-'05 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC299**<br><br>**PIC101** | **Nissan**<br>22448-8H300, 22448-8H310<br>22448-8H311, 22448-8H314<br>22448-8H315, 22448-9Y600<br>22448-6N200, 22448-6N210<br>22448-6N215, UF350<br><br>Altima '02-'06<br>Sentra '02-'06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC300** | **Nissan**<br>22448-8J110, 22448-8J111<br>22448-8J115, 22448-8J11C<br>22448-8J225, 22448-AL500<br>22448-AL510, 22448-AL515<br>22433-8J115, 22433-8J11C<br>33400-82Z10<br><br>Pathfinder 4.0L V6 '05-'12<br>Infiniti I35 3.5L V6 '02-'04<br>Murano 3.5L V6 '03-'07 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC302** | **VW**<br>021905105C<br>021905106B<br>UF338, C1320<br><br>Golf 2.8L V6 '99-'01<br>Jetta 2.8L V6 '99'01 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC303** | **Toyota**<br>90080-19016<br>90919-02234<br><br>Lexus ES300 '99-'03<br>Lexus RX300 '99-'03<br>Avalon '00-'4<br>Camry '00-'05<br>Sienna '01-'03 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC307** | **GM / Opel / Holden**<br>90541062, 90563160,<br>1208075, 1012080075<br>0221503017<br><br>Vectra '95-'00<br>Calibra '93-'97<br>Cadillac Catera V6-3.0L<br>'98-'97 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC308** | **Hyundai / Kia**<br>27301-23400<br>27301-23410<br>0119-6-21278<br><br>Hyundai Santa Fe<br>Kia Clarus '96-'98<br>Kia Shuma '97-'04<br>Kia Carens '00-'04 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC310** | **Fiat**<br>46777286<br>0986 221042<br><br>Multipla '00-'10<br>Stilo '01-'08<br>Palio '96-'12<br>Marea '00-'07<br>Siena '00-'04 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC312**<br><br>**PIC261** | **Toyota/ Daihatsu**<br>19070-BZ040<br>JK099700-0990<br>20181-CE121<br><br>Avanza 3SZ '06-<br>Liteace '08-<br>Perodua Myvi |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC313**<br><br>**PIC382** | **Suzuki / GM / Daewoo**<br>33410-86Z10<br>19005277<br>25181813<br>96414260<br><br>Verona '06- |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC314** | **Mercedes Benz**<br>000 158 7803<br>0221 503 035<br><br>430 '98-'02<br>E320 '96-'03<br>S350 '02-'05<br>C 280 '97-'01<br>E320 4-matic '96-'03<br>CLK 500 '03-'10 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC315** | **Lada**<br>406.3705<br>3012.3705<br>1.3012.3705<br><br>Eng ZMZ 405, 406, 409<br>1111 OKA UAZ 3160 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC316**<br>**PIC394** | **Toyota**<br>90919-02230<br>90919-02249<br>90919-02259<br>90080-19027<br><br>Lexus LS430 4.3L '01-'06<br>Lexus LX470 4.7L '98-'07<br>Sequoia 4.7L '01-'09<br>Land Cruiser 4.7L '98-'07<br>4Runner 4.7L '03-'09 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC317** | **Peugeot / Citroen**<br>597075, 597098<br>9634131480<br>94632641, 96341314<br>96632641<br><br>Peugeot 307 '00-'08<br>Peugeot 407 '04-<br>Citroen C5 '01-'04<br>Citroen Xsara '00-'06<br>Fiat Scudo '00-'06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC318** | **Peugeot / Citroen**<br>597087, 5970A0<br>9656695780<br><br>Peugeot 308 '08-<br>Peugeot 407 '05-'08<br>Citroen C5 '04-'08<br>C4 Picasso '07-<br>Jumpy Box '07- |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC319** | **Peugeot**<br>9654814480<br>26951960-3 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC321** | **Hyundai / Kia**<br>27301-26600<br><br>Accent II 1.5L '00-'05<br>Elantra 1.6L '00-'06<br>Matrix 1.6L '01-'10<br>Getz 1.6L '02-<br>Cerato 1.6L '04-<br>Rio II 1.6CVVT '05- |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC322**<br>**PIC291** | **Chery**<br>A11-3705110EA<br><br>0221 503 465 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC323**<br>**PIC273** | **Renault / Nissan**<br>7700875000<br>7700107177<br>0986221001<br>22448-00QAA<br><br>Renault Trafic '01<br>Laguna '93-'01<br>Espace '96-'05<br>Nissan Kubistar '03 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC325** | **Fiat**<br>46480361, 46446039<br>46472440, 500309816<br>7789346, 060792001010<br>0986221003<br><br>Brava 1.6<br>Marea 1.6<br>Multipla 1.6<br>Palio Weekend 1.6 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC328**<br>**PIC209** | **Honda**<br>30500-P2A-J01<br>**Hitachi**<br>CM1T-230, CM1T-230A<br>CM1T-231, CM1T-231S<br><br>Infiniti QX4 3.3L V6<br>Frontier 3.3L V6<br>Pathfinder 3.3L V6 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC330** | **Audi / VW**<br>036 905 715<br>036 905 715A /C /E /F /G<br>036 905 100A /B /C /D /E<br><br>A3/S3 1.6FSI '04-'13<br>Tiguan 1.4TSI '08-'13<br>Golf 1.4 '03-'13<br>Scirocco 1.4TSI '09-'12 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC331** | **Toyota / Daihatsu**<br>90919-52127<br>90048-52127<br><br>Terios J1 1.3L |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC332** | **Toyota / Daihatsu**<br>19500-B0010<br>90048-52130<br><br>Avanza '02-<br>Xenia '02- |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC334** | **Mitsubishi / GM**<br>MD-314582<br>88921388<br><br>Montero 3.0L '97-98<br>Montero Sport 3.0L<br>'99-'03<br>Montero Sport 3.5L<br>'99-'04 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC335** | **Mitsubishi / GM**<br>MD-314583<br>88921387<br><br>Montero 3.5L V6 '97-'02<br>Montero Sport 3.0L V6<br>'97-'03<br>Montero Sport 3.5L V6<br>'99-'03 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC336** | **Nissan**<br>22448-ED800<br>22448-CJ00A<br>F01R00A067<br>**Mitsubishi**<br>1832A015<br><br>Lafesta '05<br>Bluebird '05-'12<br>Juke '10-'13<br>Sylphy '05-'12<br>Renault Clio '05 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC337** | **Ford / Mazda**<br>4W5G-12A366-BA<br>4M5G-12A366-BB<br>4M5G-12A366-BD<br>4M5Z-12029-A<br>4M5Z-12029-BA<br>4M5C-12A366-BC<br>DG-501, DG-504<br>DG-507, DG-537<br>DG-541<br><br>Ford Focus 2.0L '04-'11<br>Mazda 3 2.0L/2.3L '04-'05 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC338** | **Chevrolet**<br>55570160<br>96476979<br><br>Cruze 1.6T '09-'12<br>Orlando '11<br>Lacetti '05<br>Aveo '06<br>Nubira '05-'06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC339** | **Ford / Mazda**<br>4M5G-12029-ZA<br>4M5G-12029-ZB<br>CM5G-12029-FA<br>CM5G-12029-FB<br>1350562, 1459278<br>BE8Z-12029-Z<br>C401-18100-A<br>DG-545<br><br>Ford Fiesta 1.6L '11-'14 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC341** | **Porsche**<br>906 602 101 01<br>906 602 102 00<br>906 602 103 01<br>996 602 101 01<br>996 602 102 00<br>997 602 107 00<br><br>Boxster '97-'03<br>911 '99-'01 |

MOQ: 50pcs



*2 Fitment Holes - 3 pins*

| Part No.: | Application: |
|---|---|
| **PIC342** | **Mitsubishi**<br>MD362903<br>**Marelli**<br>060717107012 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC344** | **Daewoo / GM**<br>111546<br>01115467<br>96165049 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC345** | **Audi / VW**<br>06A905115<br>06A905115A<br>06A905115B<br>06B905115H<br>06B905115L<br>06B905115R<br><br>Audi A4 Quattro 1.8L '01-'05<br>VW Passat 1.8L '01-'05 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC346**<br>**PIC242** | **Mazda**<br>B6S7-18-100, B6S7-18-10XA<br>B6S8-10-10XA, B6S8-18-10XA<br>F269-18-10X, F269T18-10X<br>**Ford**<br>F0BZ-12029-A<br>F0C6-12029-AA<br>F1CZ-12029-A<br><br>Mazda Protege 1.8L '94<br>Mazda B2200 2.2L '93<br>Ford Escort 1.8L '92 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC348**<br>**PIC166** | **Lada**<br>2111-3705010<br>2111-3705010-03<br>F000 ZS0 211<br>Bosch 0221 504 461 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC352** | **Nissan / Toyota / Ford / Fiat**<br>C6R-800 |

MOQ: 100pcs

| Part No.: | Application: |
|---|---|
| **PIC353** | **Nissan**<br>22448-6N000, 22448-6N001<br>22448-6N002, 22448-6N010<br>22448-6N011, 22448-6N012<br>22448-8U115, 22448-6N015<br>22433-6N015, 1N04-18-100<br><br>Sentra 1.8 '01-'06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC356** | **Proton**<br>PW812018<br><br>Persona Gen 2<br>Saga BLM |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC358**<br>**PIC360** | **GM**<br>12629037<br>0221 604 112<br>71753911, D501C<br><br>Buick Rendezvous 3.6L ‘04-’06<br>Cadillac SRX 3.6L ‘04-’06<br>Buick Enclave 3.6L ’09<br>Chevrolet Traverse 3.6L ‘09<br>Chevrolet Vectra 2.8L ‘08 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC361** | **GM**<br>12566589,12632479<br>099700-1510<br>12590990, 12610626<br>D508C<br><br>GMC Acadia V6 3.6L ‘07-’08<br>Buick Enclave V6 3.6L ’08<br>Chevrolet Equinox V6 3.6L 08-’09<br>Suzuki Grand Vitara V6 3.6L ‘09-‘10 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC363** | **Ford**<br>3L3Z-12029-BA<br>3L3E-12A366-CA<br>3L3U-12A366-BB<br>5C3E-12A366-AA<br>5C3E-12A366-AA1<br>112029340, DG-511<br><br>F-250 5.4L V8 ‘05-’08<br>F-550 6.8L V10 ‘99-’07<br>Mustang 4.6L V8 ‘05-’08<br>Expedition 5.4L V8 ‘05-’08 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC365** | **Isuzu / Chevrolet / GM**<br>8-12568-062-0, 19300921<br>12568062, 028310, 028315<br><br>Colorado 3.5L ‘04-’06<br>Buick Rainer 4.2L ‘04-’05<br>Hummer H3 3.5L ‘06<br>Isuzu Ascender 4.2L ’03-’05<br>GMC Canyon 2.8L ‘04-’06 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC367** | **Hyundai**<br>27301-22600<br><br>Atoz 1.3L ‘03-’08<br>Accent II 1.3L ‘00-’05<br>Accent II Saloon 1.3L ‘00-’05<br>Getz 1.3i ‘02-’04<br>Getz 1.3L ‘03-’09 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC368** | **Suzuki**<br>33400-65J00<br><br>SX4 2.0L ‘07-’09<br>Grand Vitara 2.7L ‘06-’08 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC369** | **Toyota**<br>90919-02250, 90919-02256<br>90919-02257, 90919-T2004<br>90919-A2003, 90919-A2005<br><br>Land Cruiser 5.7L V8 ‘08-’09<br>Lexus GS300 3.0L V6 ‘06<br>Lexus LS460 4.6L V8 ’07-’08<br>Sequoia 5.7L V8 ‘08-’09<br>Tundra 5.7L V8 ‘07 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC370** | **Mitsubishi**<br>MR994642, MR994643<br>SMW250746, 6Y081028<br><br>Galant ‘04-’12<br>Eclipse L4-2.4L 09-’11<br>Lancer ‘04-’06<br>Outlander ‘04-’06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC371** | **Hyundai / Kia**<br>27300-26640, 27301-26620<br>27301-26640, 03220-10874<br><br>‘06-’11 Accent 1.6L<br>‘06-’10 Dodge Attitude1.6L<br>‘06-’11 Rio 1.6L<br>‘06-’11 Rio 5 1.6L |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC372** | **Hyundai / Kia**<br>27301-3C000<br>27301-3C010<br><br>Genesis '08<br>Sonata '05-'12<br>Grandeur '05-'07<br>Sorento '06-'09<br>Sportage '10<br>Carnival '05-'10 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC373** | **Toyota**<br>90080-19017<br>90080-19018<br>0221504020<br><br>Passo '05-'10<br>Corolla '00-'07<br>Auris '07<br>Yaris '05-'11 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC374** | **Honda**<br>30520-P8E-A00, 30520-PDK-A01<br>30520-PGK-A00, 30520-PGK-A01<br>30520-PVF-A01, 30520 PVJ A01<br>30520-RDJ-A01, 30520-PYJ-A01<br><br>Pilot 3.5L '03-'05<br>Acura MDX 3.5L '01-'05<br>Ridgeline 3.5L '06-'08<br>Civic 1.7L '01-'05 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC375** | **Daewoo / Chevrolet**<br>96453420<br><br>Nubira Saloon 1.6L '03-<br>Nexia Saloon 1.6L '08-<br>Aveo Saloon 1.6L '05-<br>Optra 1.6L '03-'08<br>Cruze 1.6L '09- |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC376** | **Renault / Dacia**<br>6000592931<br>6001544755<br><br>Logan 1.4L '04-'09<br>Sandero '08-<br>Logan MCV '07-<br>Solenza '03- |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC377** | **Nissan**<br>22448-AX001<br><br>Marelli<br>060810160010<br><br>Micra III (K12) '03-'10<br>Micra C+C '05-<br>Note '06-<br>Cube '03-'05 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC378** | **Toyota**<br>90919-02238<br>90919-02238A<br>099700-0510<br>099700-0511<br>099700-0512<br><br>Corolla 1.8L '04-'06<br>Matrix 1.8L '03-'06<br>Celica '00-'05 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC379** | **Mazda**<br>ZJ20-18-100<br>ZJ20-18-100A<br>ZJ49-18-100<br>ZJ49-18-100A<br>5-099700-087<br><br>Mazda 2 1.5L '11-'14 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC380** | **Opel / GM / Fiat**<br>1208021, 10458316<br>11040825, 71739725<br>7173725, 71744369<br><br>Chevrolet Astra '00-'08<br>Chevrolet Zafira '02-'05<br>Chevrolet Vectra '03-'05<br>Saturn Astra '08-'09 |

MOQ: 50pcs

# IGNITION COILS




| Part No.: | Application: |
|---|---|
| **PIC381** | **Hyundai / Kia**<br>27301-2B100<br><br>Accent '12-'13<br>Rio5 '12-<br>I40 '11-'12<br>Sportage '11- |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC382** | **Suzuki / GM / Daewoo**<br>33410-86Z10<br>19005277<br>25181813<br>96414260<br><br>Verona '06- |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC383** | **GM / Chevrolet**<br>55570160, 55571790<br>26163171, 25186686<br>96476979<br><br>Aveo '05-'11<br>Nubira '05-'10<br>Pontiac Sport (Rear)<br>'09-'12 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC384** | **GM / Chevrolet / Opel**<br>1208086, 55561655<br>96476983, 25186687<br><br>Chevrolet Trax '12-'13<br>Chevrolet Cruze '09-'14<br>Opel Mokka '12-'13<br>Pontiac G3 '09-'10<br>Vauxhall Astra '04-'12 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC385** | **Ford / Mazda**<br>1053904, 1067601 1075786,<br>1119835 1130402, 1317972<br>1319788, 1619343 12029AB<br>988F-12024-AB, 988F12024AB<br>988F-12029-AD, 988F12029AD<br>1F20-18-100, LF01-18-100<br><br>Focus DW, DNW 1.4/ 1.6/ 1.8/ 2.0<br>Mondeo III B4Y, BWY 1.8/ 2.0 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC386** | **Audi / VW**<br>07K 905 715<br>07K 905 715A<br>07K 905 715B<br>07K 905 715C<br>07K 905 715D, E, F<br><br>Audi A4 2.0T '05-'12<br>Audi Q5 2.0T '11-'12<br>VW Golf 2.5T ' 10-'12 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC387** | **Hyndai / Kia**<br>27301-2B000<br><br>Hyundai i20 '08<br>Hyundai i30 '07-'12<br>Kia Soul '09-'12<br>Kia Carens '09-'10 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC388**<br>**PIC215** | **Toyota**<br>90919-02215<br>90080-19012<br><br>Lexus ES '91-'08<br>Kluger '00-'07<br>Avalon '96-'99<br>Camry '91-'08<br>Harrier '98-'08<br>Alphard '03-'08 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC389** | **Toyota**<br>90919-02216<br>90919-11007<br><br>Supra 3L '98<br>Lexus GS300 3L '98-'05<br>Lexus IS300 3L '01-'05<br>Lexus SC300 3L '98-'00 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC390** | **Toyota**<br>90919-02246<br>90080-02246<br><br>Lexus ES330 V6-3.3L<br>Lexus RX330 V6-3.3L<br>'04-'06<br>Sienna V6-3.3L '04-'06<br>Camry V6-3.3L '04-'06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC391** | **Audi / VW**<br>06C905115 A/ B/ D<br>06C905115 E/ F/ G<br>06C905115 H/ K/ L<br>077905115 Q<br><br>A8 3.0 V6 '03-'07<br>A4 3.0 V6 '01-'08<br>A6 3.0 V6 '02-'08 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC392** | **Honda**<br>30520-PWC-003<br>30520-PWC-013<br>30520-PWC-S01<br>30520-PWC-501<br>30521-REA-Z01<br>30520-REB-Z01<br>CM11-110<br><br>Fit 1.5L '07-'08 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC393** | **Suzuki**<br>33400-76G00, 33400-76G01<br>33400-76G11, 33400-76G20<br>33400-76G21, 33400-81A00<br>33400-76G30, 33400-50F20<br>33400-85K00, 33400-85K10<br>099700-095<br><br>Wagon R+ '98-'03<br>Alto '94-'02 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC394**<br>**PIC316** | **Toyota**<br>90919-02230<br>90919-02249<br>90919-02259<br>90080-19027<br><br>Lexus LS430 4.3L '01-'06<br>Lexus LX470 4.7L '98-'07<br>Sequoia 4.7L '01-'09<br>Land Cruiser 4.7L '98-'07<br>4Runner 4.7L '03-'09 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC395**<br>**PIC11** | **Toyota**<br>90919-02229<br>90919-02240<br>90919-02265<br>90080-19021<br>099700-0272<br>099700-0524<br>099700-1880<br><br>Prius 1.5L '01-'09<br>Yaris 1.5L '06-'10 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC396**<br>**PIC259** | **Toyota**<br>90919-T2001, 90919-T2005<br>90919-T2008, 90919-A2001<br>90919-A2006, 90919-C2002<br>90919-C2006, 90919-02247<br>90919-02248, 90919-02260<br><br>Scion TC '05-'10<br>FJ Cruiser '07-'09<br>Tacoma 2.7 '05-'10<br>Camry 2.4 '07-'09 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC397** | **Toyota**<br>90919-02252, 90919-02258<br>90919-C2003, 90919-C2005<br>099700-1081, 099700-1230<br>099700-1530, 099700-1531<br><br>Matrix 1.8L '09-'10<br>Corolla 1.8L '08-'13<br>Pontiac Vibe 1.8L '09-'12<br>Scion xD 1.8L '08-'12 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC398** | **Honda**<br>30520-RNA-A01<br>099700-101, 099700-102<br><br>Civic 1.8L '06-'11 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC399** | **Honda**<br>30520-R40-00<br>099700-147<br>099700-148<br>099700-149<br><br>Accord 2.4L '08-'11<br>CR-V 2.4L '10-'11 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC400**<br>**PIC248** | **Honda**<br>30520-PMA-007<br>30520-PNA-007<br>30520-PRA-007<br>30520-PWA-007<br>30520-RAA-007<br>30520-RRA-007<br><br>Accord 2.4 L4 '03-'05<br>Civic '02-'05<br>CR-V '02-'06<br>Acura RSX '02-'06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC401** | **Nissan**<br>22448-7S015<br>22448-AR215<br><br>Pathfinder 5.6 '04<br>Infiniti QX56 5.6 '04-'06<br>Titan 5.6 '04-'06<br>Armada 5.6 '05-'06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC402** | **Honda**<br>30520-P8E-A01<br>30520-RCA-A02<br><br>Accord 3.0L V6 '00-'03<br>Acura TL 3.2L V6 '99-'03<br>Odyssey 3.5L V6 '99-'09<br>Acura CL 3.2L V6 '01- '03 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC403** | **Toyota**<br>90919-02237<br><br>Tacoma 2.7 '99-'04<br>4Runner 2.7 '99-'00 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC404** | **GM**<br>96983945<br>9023781<br>BDW-IC-049<br>A0991600089<br><br>Holden Barina Spark MJ<br>1.2L '10<br>Chevrolet Spark 1.2L '13 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC405** | **Opel**<br>1208012, 90543253<br>0221503015<br><br>Astra G 1.2 16V '98-<br>Corsa B 1.2 16V '98-<br>Corsa C 1.2 16V '98- |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC407**<br>**PIC423** | **GM / Chevrolet / Opel**<br>12578244, 12638824<br>12589623, 12629646<br>1208089, 4802236<br>4805094, 099700-0860<br><br>Buick Regal 2L '11<br>Pontiac G5 2.2L '07-'10<br>Malibu 2.4L '08-'11<br>Cobalt 2.4L '06-'08 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC408** | **Renault**<br>8200 360 911<br>8200 702 693<br>H8200734204<br><br>Kangoo '01<br>Modus '04-'08<br>Thalia '02-'08<br><br>*Remarks:*<br>for complete set with cables.<br>Refer to PIC255 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC409** | **GM / Daewoo**<br>96415010<br>BK 4391<br><br>Chevrolet Optra '03-'08<br>Chevrolet Nubira '05<br>Chevrolet Cruze '09<br>Daewoo Lacetti '03-'08<br>Daewoo Nubira '03 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC411** | **VW / Skoda**<br>047 905 104A<br>047 905 104B<br>060796105010<br>905077001<br>ZSE040, BAE961AE<br><br>Lupo 6X1, 1.0 '10-'05<br>Fabia 6Y2 1.0 '99-'08<br>Felicia I 6U1 1.3 '94-'98<br>Octavia 1U2 1.4 16V '00 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC412** | **VW**<br>066 905 100<br>066 905 100B<br>066 905 100C<br>066 905 100D<br>066 905 100G<br><br>Passat 2.3L V5 '00-'05<br>Passat Variant 2.3L VR5 '00-05 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC413** | **BMW**<br>1748017, 1748018,<br>12131404309<br>12131703227<br>12131703825<br>12131748017<br>12139067830<br><br>323 M52 '97-'00<br>850 M62 '96-'99<br>525 i M50 '89-'95<br>X5 3.0i V6 '00-'06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC415** | **Lada**<br>2112 12494<br>2112 3705010 SL<br><br>0221 504473<br><br>Priora Saloon 1.6<br><br>*Remarks:*<br>AV |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC416** | **Nissan**<br>22448-AL600, 22448-AL610<br>22448-AL615, 22448-AL61C<br>22433-AL615, 22433-AL61C<br><br>Infiniti M35 3.5L V6 '06-'08<br>Infiniti FX35 3.5L V6 '03-'09<br>Infiniti G35 3.5L V6 '03-'07<br>Nissan 350Z 3.5L V6 '03-'06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC417** | **Nissan**<br>22448-EA000, 22448-ED000<br>22448-JA00A, 22448-JA00C<br>22448-JA10C, 22448-EN000<br>22448-EN200, 22448-1HC0A<br>22448-1KT1A<br><br>Quest 3.5 '11-'12<br>Infiniti FX50 5 '10<br>Maxima 3.5 '08-'12<br>350Z 3.5 '07-'09<br>Murano 3.5 '09-'12 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC418** | **Mazda / Ford**<br>L3G2-18-100A<br>6M8G-12A366<br><br>Mazda 6 2.3L '06-'08<br>Mazda 3 2.0L '06-'10<br>CX-7 2.5L '10<br>MX-5 2.0L '06-'09 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC419**<br>**PIC481** | **Nissan**<br>22448-1KC0A, 22448-1KCOA<br><br>Juke 1.6L '11-'17<br>Sentra 1.6L '11-'17 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC420**<br>**PIC186** | **Mazda**<br>ZZY1-18-10<br>ZL01-18-100<br>ZL01-18-100A<br>JJY1-18-100<br><br>323 1.5L '98-'01<br>MX-5 1.8L '01-'05<br>323 1.6L '01-'04<br>Miata 1.8L '01-'05 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC421** | **Subaru**<br>22433-AA230<br>22433-AA360<br>88921342<br><br>Impreza 1.8L '93-'97<br>Legacy 2.2L '90-'94 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC422** | **Subaru**<br>22433-AA240<br>22433-AA370<br><br>Forester 2.5L '98-<br>Impreza 2.5L '98-<br>Impreza 2.2L '95-'96<br>Legacy 2.5L '96<br>Legacy 2.2L '94 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC423**<br>**PIC407** | **GM / Chevrolet / Opel**<br>12578244, 12638824<br>12589623, 12629646<br>1208089, 4802236<br>4805094, 099700-0860<br><br>Buick Regal 2L '11<br>Pontiac G5 2.2L '07-'10<br>Malibu 2.4L '08-'11<br>Cobalt 2.4L '06-'08 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC424** | **Rover**<br>0040100501000<br>000120, 000120L<br><br>Rover 400 1.6L '95-'00<br>Rover 400 (RT) '95-'00<br>Rover 25 (RF) '99-'05<br>Cabriolet 1.6L '96-'99<br>MG ZS '01-'05<br>MG ZT- T '03-'05 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC425** | **Chrysler**<br>04606869AA<br>04606869AB<br>04606869AD<br>7B0905715<br>80472800169<br><br>Sebring V6 3.5L '07-'10<br>Pacifica V6 4.0L '07-'08<br>VW Routan V6 4.0L '09-'10 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC426** | **Mitsubishi**<br>MN195616<br>MN195452<br>MN195805<br><br>Lancer '10-<br>Colt VI '04-<br>Colt VI '08-<br>Berlina '10<br>Smart for Four 1.5L '04-'06 |

MOQ: 50pcs

*Length: 149mm*



| Part No.: | Application: |
|---|---|
| **PIC427** | **Mitsubishi**<br>1832A025<br>MQ300200<br><br>Lancer 2.0L L4 '05-'10<br>Lancer 2.4L L4 '09-'11<br>Outlander 3.0L V6 '07-'11 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC428** | **VW / Chrysler**<br>5603250, 53006565<br>560298AA, 56032520AB<br>56032520AC, 56032520AE<br>56032520AF, 7B0905115<br><br>Voyager V6 3.3L '01-'03<br>VW Routan V6 3.8L '09-'10<br>Town & Country V6 3.8L '01-'10 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC429** | **Hyundai / Kia**<br>27300-2E000<br><br>Hyundai i40 '11-'14<br>Hyundai Trajet '03-'08<br>Elantra '13-'11<br>Sonata '08-'14<br>Kia Soul '09-'11<br>Carens '13<br>Kia Forte '14 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC430** | **Hyundai / Kia**<br>27301-3E400<br>27301-3E410<br><br>Grandeur '06-'11<br>Magentis '05<br>Santa Fe '07-'09<br>Tiburon '06<br>Optima '07-'10 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC431** | **Nissan**<br>22448-JA10A<br>22448-JA10C<br><br>Infiniti G25 2.5L '11<br>Infiniti FX35, EX35 '11<br>Murano 3.5L '12 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC432** | **Hyundai / Kia**<br>27301-03110<br><br>i10 '08-'11<br>i20 '08-'09<br>Picanto '09-'11<br>Rio III '09-'11 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC433** | **Hyundai / Kia**<br>27301-2B010<br>CM11-116<br><br>i20 1.4/1.6L '08-<br>i30 1.4/1.6L '07-'08<br>Cee'd 1.4/1.6L '06<br>Cerato 1.6 '04<br>Soul '10 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC434** | **Toyota**<br>90919-02224<br><br>Corolla 1.8L '98-'00<br>Vista '06-'07<br>Prizm '98-'99<br>Verso .18 '02-'04 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC435** | **Toyota**<br>90919-02251, 90919-02255<br>90919-A2002, 90919-A2004<br>90919-A2007, 90919-569F0<br><br>Highlander 3.5L V6 '08-'16<br>RAV4 3.5L V6 '06-'12<br>Venza 3.5L V6 '09-'15<br>Camry 3.5L V6 '07-'16 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC436** | **Mazda**<br>N3H1-18-100<br>N3H1-18-100A<br>N3H1-17-100C<br>N3H1-18-100-9U<br>N3H1-18-100A-9U<br><br>RX-8 1.3L '04-'09 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC437** | **Hyundai / Kia**<br>27301-04000<br><br>Picanto 1.0 '11<br>i10 G3LA |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC438** | **Nissan**<br>22448-1F700<br>0221 504017<br><br>Micra II '00-'03 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC439** | **Mazda**<br>ZJ01-18-100<br>ZJ01-18-100A<br><br>Mazda 3 '03-'06 |

MOQ: 50pcs



*2 Fitment Holes - 3 pins*

| Part No.: | Application: |
|---|---|
| **PIC441** | **Mitsubishi**<br>MD362903<br>**Marelli**<br>060717107012 |

MOQ: 50pcs

*4 pins*

| Part No.: | Application: |
|---|---|
| **PIC442** | **Daihatsu / Toyota**<br>19070-B1020<br><br>Copen '06-'14<br>Sirion '00-'05<br>Bego '05<br>Materia '06-'14<br>Xenia '02-'07<br>Toyota Rush 3SZVE<br>J200 |

MOQ: 50pcs



*3 pins*

| Part No.: | Application: |
|---|---|
| **PIC443** | **GM / Isuzu**<br>12496547, 12596547<br>12612369, 12629472<br>8125965470<br><br>Chevy Colorado 2.9L '07-'10<br>GMC Envoy 4.2L '06-'09<br>Hummer H3T 3.7L '09<br>Isuzu Ascender 4.2L '06-07<br>Trailblazer EXT 4.2L '06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC444** | **Nissan**<br>22448-4W011<br><br>Infiniti QX4 3.5L V6 '01<br>Pathfinder 3.5L V6 '00-'01 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC446** | **Hyundai / Kia**<br>27301-3F100<br><br>Sonata '08-'15<br>Genesis Coupe '10-'14<br>Tucson '10-'15<br>Santa Fe '10-'14<br>Kia Forte '10-'13<br>Kia Optima '09-'15 |

MOQ: 50pcs

*2 pins*

| Part No.: | Application: |
|---|---|
| **PIC447** | **BYD**<br>KRK 120706BH<br><br>BYD F3 1.6 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC448** | **Subaru**<br>22433-AA610<br><br>Tribeca 3.6L '10-'16<br>Legacy 3.6L '10-'16<br>Outback 3.6L '10-'16 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC449** | **Honda**<br>30520-RBJ-003<br>30520-RBJ-013<br>30520-RBJ-S01<br><br>City 1.5L '10-'13<br>Insight 1.3L '10-'11 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC450** | **Mitsubishi**<br>MD362913<br>MD366821<br><br>Galant 1.8L '97-'00<br>Diamante 3.0L '97-'00<br>Pajero V75W 3.5L '97-'05<br>Lancer Cedia 1.8L '00-'07 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC451** | **Ford**<br>DS7G-12A366-BB<br><br>Escape 1.5L '13-'17<br>Fusion 1.5L '13-'17 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC452** | **Mercury / Ford**<br>OK-15-131708<br>8M0039809<br><br>Mariner / Mercury<br>4-Strokes<br>75, 80, 90, 100, 115 EFI<br>135, 150, 200, 225,<br>250 275, 300 Verado<br>300 Pro Verado,<br>Outboard 2.6L '05-'06 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC453** | **Hyundai / Kia**<br>27301-37150<br>01122-0400<br><br>Coupe '02-'09<br>Trajet '00-'08<br>Sonata '01-'04<br>Santa FE '01-'06<br>Sportage '04-'10 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC454** | **Hyundai**<br>27301-37110<br>27301-37120<br>27301-37115<br>27301-37116<br>27301-37117<br><br>Coupe '02-'09<br>Sonata '01-'06<br>Tucson '04-'10 |

MOQ: 50pcs

*2 pins*

| Part No.: | Application: |
|---|---|
| **PIC455** | **Mitsubishi**<br>MW250963<br><br>4A91 |

MOQ: 50pcs



*3 pins*

| Part No.: | Application: |
|---|---|
| **PIC456** | **Suzuki**<br>33400-M68-K00<br><br>Alto<br>Celerio |

MOQ: 50pcs

*4 pins*

| Part No.: | Application: |
|---|---|
| **PIC457** | **Toyota**<br>90919-02245<br><br>Yaris 12-06<br>RAV4 04-00, 4Runner 09-05<br>Corolla 09-01, Celica 05-99<br>Land Cruiser 100 HDJ101<br>6cyl 4.2 TD Diesel 07-98<br>LEXUS LX470 07-98,<br>LS430 06-04<br>GS300 05-97, IS300 05-04 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC458** | **Chevrolet**<br>19005362, 25195107<br>25198623, 36-8272<br>52-2205, 5557549<br><br>Cruze '11-'20 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC459**<br>**PIC479** | **Mazda**<br>PE20-18-100A<br><br>Mazda CX-5 '13-'15<br>Mazda 3 '12-'15<br>Mazda 6 '13-'15 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC460** | **Mercedes Benz**<br>A0001502780<br>68139957AA<br>19005267<br>UF-535, UF535<br><br>W203, C280, C300<br>C350, E350, E550<br>'11-'12 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC461** | **Subaru**<br>22433-AA540<br>22433-AA641<br>22433-AA480<br><br>Forester, Impreza,<br>Legacy 2.5L H4 Turbo |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC462** | **Chery**<br>E4G13-3705110<br>F01R00A041<br><br>A3 Tiggo<br>Arrizo 5 7 1.6L VVT '10 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC463** | **Mitsubishi**<br>1832A057<br>1832A062<br><br>Mirage 1.2L L3 '14-'18<br>Mirage G4 '17-'18 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC464** | **Nissan**<br>22448-1KT0A<br><br>Juke, Micra III IV<br>Note, Qashqai,Tiida<br>NV200 1.2L 1.6L |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC465** | **Honda / Acura**<br>30520-5A2-A01<br><br>Acura ILX Saloon 2.4 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC466** | **Honda**<br>30520-R40-007<br>099700-070<br>099700-148<br><br>Accord, Civic, CR-V |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC467** | **Nissan**<br>22448-1HC0A<br><br>Almera N17 1.5 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC468** | **Honda**<br>30520-55A-003<br>30520-55A-005<br><br>Jazz '14<br>BRV '14 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC469** | **Renault**<br>22448-00QQA<br>22448-00QAC<br>22448-00QAE<br><br>Clio II III,<br>Espace III IV,<br>Laguna I II,<br>Megane I II<br>'97- |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC470** | **Toyota**<br>90919-02263<br><br>Etios Liva Cross<br>1NRFE, 2NRFE, 3NRFE |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC471** | **Hyundai**<br>27301-03010<br><br>i10, i125 1.2L '14 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC472** | **Audi / VW**<br>06F905115A<br><br>A3, A4, A5, A6, A8,<br>Q3, Q5, TT<br>Golf, Jetta, Passat,<br>Scirocco, Tiguan, Toureg |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC473** | **Ford**<br>CM5G-12A366-CB<br>CM5G-12A366-CB<br>CM5G-12A366-CA<br>DG553, DG556,<br>CM5Z-12029-C<br><br>Fiesta 1.0<br>EcoSport '18 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC474** | **Ford**<br>CM5G-12029-ZA<br>CM5G-12029-FA<br>UF740<br><br>Fiesta '11-'15 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC475** | **Ford**<br>3W7Z-12029-AA<br>8W7E-12A366-AA<br><br>Mercury<br>DG467, DG491<br>DG508, FD503 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC476** | **Ford**<br>8L3Z-12029-A<br>8L3E-12A366-AA<br>DG521<br><br>Lincoln Expedition<br>F450 F550<br>Super Duty Navigator<br>4.6L 5.4L 6.8L |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC477** | **Ford**<br>7T4Z-12029-E<br>DG520<br><br>Flex, Taurus, Edge<br>Lincoln MKS, MKT,<br>MKZ, MKX<br>Mercury Sable 3.5L V6 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC478** | **Suzuki**<br>33400-51K20<br>33400-51K40<br><br>Grand Vitara SX4<br>Swift, Liana 1.6<br>M16A |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC479**<br>**PIC459** | **Mazda**<br>PE20-18-100A<br><br>CX-5 '13-'15<br>Mazda 3 '12-'15<br>Mazda 6 '13-'15 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC480** | **Mitsubishi**<br>1832A067<br>1832A057<br>1832A032<br>1832A062<br><br>Outlander<br>Mirage G4<br>1.2L '14-'17 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC481** | **Nissan**<br>22448-1KC0A<br><br>Juke 1.6L '11-'17<br>Sentra 1.6L '17-'19<br>Rogue Sport 2.0L '17-'20<br>Teana L33 2.0L<br>Serena C26 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC482** | **Nissan**<br>22448-1LA0A<br>22448-1LA0B<br><br>Infiniti QX56 V8 5.6L '11 -'13<br>Infiniti QX80 V8 5.6L '14 -'16<br>Armada V8 5.6L '17- '19 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC483** | **Nissan**<br>22448-JN10C<br><br>Altima, Maxima,<br>Murano G35 G37<br>V6 3.5L '03-'06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC484** | **Hyundai / Kia**<br>27301-03200<br><br>Accent '14-'17<br>Kia I25 1.4L<br>I30 I40 1.6L |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC485** | **Toyota**<br>90919-02235<br><br>Toyota ST210<br>Vista Ardeo SV50<br>Nadia SXN10 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC486** | **Kia**<br>5WY2809A<br>2280-5<br><br>Pride, Rio |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC487** | **Hyundai**<br>5WY2820 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC488** | **Peugeot / Citroen**<br>9629210680, 9629210681,<br>96292106, 597048,<br>597073<br><br>Peugeot 306, 406, 605, 806<br>Citroen XM, Citroen XSARA,<br>Fiat Ulysse, |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC489** | **Peugeot**<br>0221504022<br>K914560188A<br><br>Peugeot 206<br>Samand EF7 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC490** | **Honda**<br>30520-5R0-003<br>30520-5R0-013<br><br>Civic 2.0L ‘17-’18<br>Fit 1.5L ‘15-’16<br>HR-V (RU)<br>JAZZ IV (GK_) |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC491** | **Nissan**<br>22448-6CA1A<br><br>Altima 2.5L ‘19-’21<br>Rogue 2.5L ‘21 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC492** | **Geely**<br>28244734, 19005277<br>28063913<br><br>Geely EC7, GC7, GX7<br>Chana Cross V5<br>Lifan, Glory, JAC<br>J3, J4, J5 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC493** | **Toyota**<br>9004A-19002<br><br>Avanza F65<br>Rush F800<br>‘15-’17 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC494** | **Toyota**<br>90919-T2010<br><br>Sienna, Camry<br>Highlander 3.5L ‘17-’18 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC495** | **Suzuki**<br>33400-64G00<br><br>Esteem GL, GLX 1.6L '98<br>Baleno |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC496** | **Suzuki**<br>33400-62L00<br>33400-78M00<br><br>Alto 1.0L ‘09-’15<br>Alivio 1.4L,1.6L ‘15<br>S-Cross 1.6L ’14-’15<br>Vitara |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC497** | **Suzuki**<br>33400-51K00<br>33400-51K20<br><br>Grand Vitara '11<br>Kizashi 2.4L<br>SX4 2.0L L4 '12 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC498** | **Suzuki**<br>33400-75F10<br><br>Celerio<br>Swift Sport M16A<br>1.6L '12-'17 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC499** | **Mitsubishi**<br>MD-348947<br>MD-355008<br>MD-362915<br><br>Space Wagon 2.4L<br>GDI 4WD ‘98-’04<br>Galant '99-'04<br>Grandis '97-'03 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC500** | **Chevrolet / Daewoo**<br>96291054<br>0880156<br>89930267<br><br>Matiz M200, M250<br>Spark 0.8L ‘00-’04 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC501** | **Honda**<br>30520-5G0-A01<br><br>Accord, CRV EX/EX-L ‘18<br>Odyssey 3.0L, 3.5L '21-'22<br>Acura MDX 3.5L V6 ’17-’19 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC502** | **Honda**<br>30520-R1A-A01<br><br>HRV 1.8L SOHC ‘18-’20 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC503** | **Honda**<br>30520-R70-A01<br>30520-R70-S01<br><br>Accord, Odyssey<br>3.5L V6 '14-'16<br>CrossTour 3.5L V6 '12<br>Acura TL 3.5L V6 '09-'12<br>Acura RL 3.7L V6 '09-'12 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC504** | **Mitsubishi**<br>MD-309456<br>MD-339027<br><br>Delica '94-'02<br>Space Gear '94-'01<br>L200 '96-'01<br>L300 '86-'03<br>L400 '94-'01 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC505** | **Toyota**<br>90919-02277<br>90919-A2010<br><br>Camry 2.5L L4 '18-'20<br>RAV4 2.5L L4 '19<br>Avalon 2.5L L4 '19-'20<br>ES300h 2.5L L4 '19<br>LS500 3.5L V6 '18-'19 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC506** | **Hyundai / Kia**<br>27301-3CEA0<br><br>Sonata, Granduer<br>Azera 3.3L V6 '15-'17 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC507** | **Kia**<br>0K9BV-18-10X<br><br>Carnival I 2.5L V6 '99-'01<br>Carnival II 2.5L V6 '01-'06<br>Sedona MK II 2.5L V6 '01- |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC508** | **Hyundai**<br>27301-23500<br>27301-23510<br><br>Elantra 1.8L 16V '00-<br>Coupe 2.0L 16V '02-<br>Matrix 1.8L |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC509** | **Hyundai**<br>27301-23900<br><br>Avante X20 '07-'10<br>i30 (FD) 2.0L '02-'12 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC510** | **Proton**<br>PW911283<br>77258001<br><br>Iriz '14-'23<br>Persona '16-'23 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC511**<br>**PIC515** | **BMW**<br>12131712223, 12137551260<br>12131712219, 12137594935<br>12137594936, 12137594937<br>12137594938, 12138616153<br>0221504100, 0221504464<br><br>X1, X3, X4, X5, X6,<br>M3, Z3, Z4 '03-'19<br>F30, F10, R56, M54, N20<br>325Ci/ Xi '03-'04, 325i '03-'05 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC512** | **Opel**<br>1208068<br>4770046<br>0221 503002<br><br>Calibra 2.5L '90-'98<br>Saab 900 2.5L '93-'98 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC513** | **Honda**<br>30520-RB0-003<br>30520-RB0-013<br>30520-RB0-S01<br><br>City, FIT, Jazz<br>'09-'14 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC514** | **Subaru**<br>22433-AA418<br>22433-AA480<br>22433-AA540<br>22433-AA541<br>22433-AA640<br><br>Forester/Outback '04-'10<br>Impreza '07-'10 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC515**<br>**PIC511** | **BMW**<br>12138616153<br>12137575010<br>0221504800<br><br>F30 F10 N20 R56<br>330Ci '03-'04, 330i '04'05,<br>330Xi '03, 525i '03<br>530i '03 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC516** | **Toyota / Perodua**<br>19070-BZ030<br><br>Avanza, Rush F700<br>MYVI Lagi Best |

MOQ: 50pcs

*Top View (fitment hole position)*



| Part No.: | Application: |
|---|---|
| **PIC517** | **Mitsubishi**<br>0221500803<br>UF598, UF522<br><br>Lancer, BYD<br>Haima, JAC |

MOQ: 50pcs

*Top View (fitment hole position)*



| Part No.: | Application: |
|---|---|
| **PIC518** | **Mitsubishi**<br>0221500802<br><br>Lancer 4G13,<br>Hafei, BYD,<br>Wuling ZOTYE<br>1.6L, 1.8L |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC519** | **Mazda**<br>479Q-18100<br><br>Mazda, Haima |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC520** | **Hyundai / Kia**<br>27301-04110<br><br>Kona, Cee'd 1.0L '17-<br>Picanto G3LA |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC521** | **Hyundai / Kia**<br>27300-03150<br><br>Soluto<br>Verna ‘16-’17 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC522** | **Hyundai/ Kia**<br>27300-39050<br><br>Santa Fe<br>XG300 3.0L ‘01-<br>XG350 3.5L ’02-<br>Kia Sedona 3.5L ‘03-’05 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC523** | **Daewoo**<br>94582699<br>33410-A-78B00<br><br>Tico 0.8L ‘95-’00 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC525** | **Chevrolet**<br>79013001, 24585662<br>12570616, 12611424<br>8125706160<br><br>Prisma, Onix<br>GMC Yukon 6.2L V8 ‘15-’18<br>Cadillac CTS 6.0L-V8 ‘06-’07 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC526** | **Chevrolet**<br>F01R00A081<br><br>Buick Excelle 1.5L<br>Chevrolet Sail 3 1.3L |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC527** | **Chevrolet**<br>F01R00A027<br><br>N200, N300 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC528** | **Chrysler**<br>4606824AB<br>4606824AC<br><br>Dodge 2.4L ‘18-’20 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC532** | **Chrysler**<br>04609088AF<br>04609088AH<br><br>300 Series '03-'99<br>Concorde ‘03--’98<br>Intrepid ‘03--’98 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC533** | **Ford**<br>BM5Z-12029-B<br>BM5G-12A366-CA<br>BM5G-12A366-DA<br><br>Escape 1.6L '13-'16<br>Fiesta 1.6L '14-'19<br>Fusion 1.6L '13-'14<br>Transit Connect<br>1.6L '14-'16 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC534** | **GM / Chevrolet**<br>12669351<br>12619161<br><br>Chevrolet Express<br>2500 4.3L V6 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC535** | **Honda**<br>30520-PNC-004<br>30520-RWC-A01<br><br>Acura CSX 2.0L '11<br>Civic Si Coupe 2.0L '11<br>CR-V EX-L 2.4L '09 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC537** | **Proton**<br>PW812712<br>77257002<br><br>Exora Bold 1.6L Turbo,<br>Preve 1.6L Turbo,<br>Suprima S Turbo |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC538** | **Toyota**<br>90919-T2007<br><br>Vios, Yaris<br>NCP42 1.5 (2003-)<br>NCP93 (2008-)<br>NCP150, NCP151 (2014-) |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC539** | **GM / Chevrolet**<br>10489421<br>D-577<br><br>Grand Blazer Z71 '01-'04<br>Astro 4.3L V6 '96-'05 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC540** | **Isuzu / Holden**<br>8971363250<br>8971745540<br><br>D-Max '07-'13<br>Trooper 3.5L V6 '99<br>Rodeo 3.2L V6 '98<br>Jackaroo Frontera UT<br>6VD1 6VE1 3.2L, 3.5L |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC541** | **Ford**<br>BR3Z-12029-A<br>DG-542<br><br>Mustang F150 V8<br>'11-'16 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC542** | **Toyota**<br>90919-02271<br><br>Corolla E180 '14<br>Auris, CH-R '16 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC543** | **VW**<br>04E905110B, 04E905110E<br>04C905110D, 04C905110F<br>04C905110H, 04C905110J<br>04C905110K, 06H905110G<br><br>VW 1.0, 1.2, 1.4<br>'12-'17<br>Golf MK7 '14<br>Golf Polo |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC544** | **Mazda**<br>L3G2-18-100B, LFB6-18-100<br>LFB6-18-100A, LF2L-18-100A<br>LF6-18-100B, LFB6-18-100B9C<br><br>Mazda 3 2.0L '06-09<br>Mazda 6 2.5L '12-'13<br>MX-5 Miata 2.0L '14<br>CX-7 2.3L '10 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC545** | **Hyundai / Kia**<br>27301-2B120<br><br>Veloster '15-'21<br>Kona '18-'21<br>Elantra '17-'20<br>Sonata '15-'19<br>Tucson '16-'18<br>Forte/Soul 1.6L '17-'18<br>Optima 1.6L '16-'18 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC546** | **Isuzu / Honda**<br>8190052490<br>8190052500<br>8190052501<br><br>Rodeo 3.2L V6 '02-'06<br>Axiom 3.2L V6 '02-'06<br>Trooper 3.5L V6 '02<br>Passport 3.2L V6 '01-'02 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC547** | **Subaru**<br>22433-AA700<br><br>Legacy 2.5L '15-'18<br>Outback 2.5L '15-'18<br>WRX 2.0L '15-'18<br>Forester 2.0L/2.5L 17-'18 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC548** | **BMW**<br>12131712223<br>597064<br><br>325i 2.5L '03-'05<br>330ci 3.0L '03-'05<br>528i XDrive 3.0L '10<br>750i 4.8L V8 '06-'08<br>X3 3.0L '05-'06<br>X5 3.0L '03-'06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC549** | **Kia**<br>OK30E1810X<br>UF-335<br><br>Rio 1.5L '01-'05 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC550** | **Renault**<br>8200699627<br>0221504030<br><br>Fluence 2.0L '14<br>Grand Scenic 2.0L '09<br>Latitue 2.0L '11<br>Megane III '09 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC551** | **Renault / Hyundai**<br>17210-12900<br><br>SM5 (A34R)<br>SM5 (A32) |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC552** | **Renault / Hyundai**<br>17210-14900<br><br>SM5 (A32) 518 520<br>A34R L43 1.6L, 2.0L |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC553** | **Hyundai / Kia**<br>27300-2E601<br>UF-816<br><br>Elantra 2.0L '15-'19<br>Kona 2.0L '18-'19<br>Sonata 2.0L '16-'19<br>Volester 2.0L '19<br>Forte 2.0L '16-'19<br>Optima, Soul 2.0L '17-'18 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC554** | **Hyundai / Kia**<br>27300-2GGA0<br>UF-764<br><br>Azera / Grandeur '11-'14<br>Genesis 5.0L V8 '17-'20<br>Santa Fe 2.0L '18-'20<br>Sportage EX, LX 2.0L '18-'21<br>Optima EX, LX 2.0L '16-'20 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC555** | **Hyundai / Kia**<br>27301-03000<br>27301-03010<br>27301-03030<br><br>i10 1.2L '08-'13<br>i20 1.2L '08-'15<br>Santa Fe 2.7L '01-'06<br>Picanto 1.2L '11- |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC556** | **Hyundai / Kia**<br>27300-2G700<br><br>Santa Fe 2.0L '14-'16<br>Sonata 2.0L '11-'14<br>Sportage 2.0L '11-'16<br>Optima 2.0L '11-'15 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC557** | **Hyundai / Kia**<br>27301-37410<br><br>Santa Fe I 2.7L '01-'06<br>Sonata IV 2.7L '01-'04<br>Trajet 2.7L '00-'08<br>Optima '07-'09 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC558** | **Mitsubishi**<br>1832A083<br><br>Outlander PHEV 2.4L '21-'22<br>Outlander 2.0L, 2.4L '19-'21<br>Outlander Sport 2.4L '08-'17 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC559** | **Honda**<br>30520-59B-013<br>30520-59B-A00<br>UF781<br><br>Accord Hybrid 2.0L '17-'20<br>Civic 1.5L-L4 '16-'20<br>CR-V 1.5L-L4 '17-'20<br>CR-V Hybrid 2.0L-L4 '20<br>Insight 1.5L-L4 '19-'20 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC561** | **Mitsubishi**<br>1832A016<br>1832A025<br><br>Grandis '07-'08<br>Lancer '08-'15<br>Outlander '07-'16<br>Outlander Sport '11-'14<br>ASX (RVR) '11-'13 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC562** | **Nissan**<br>22448-1LA0B<br>UF677<br><br>Armada V8 5.6L '17-'19<br>Infiniti QX80 V8 5.6L '14-'19<br>Infiniti QX56 V8 5.6L '11-'13 |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC563**<br>**PIC118** | **Ford**<br>F7PZ12029AA<br>E1EF 12029 AA<br>12321405<br><br>DG-325, DG-325A,<br>DG-325ADP, DG-434,<br>DGE-453<br><br>F-350 V8 7.5L '84-'97<br>Mustang V8 5.0L '84-'95 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC564** | **BMW**<br>12137619385<br>12138647463<br><br>X3, Z4 , 230i,<br>330i. 430i '19> |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC565** | **Mercedes Benz**<br>A0001502580<br>A0001502980<br><br>C-Class<br>W203 C180<br>W204 C250<br>SLK250 '12-'15 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC566** | **Mazda**<br>PE01-18-100<br>PE02-18-100<br>PE01-18-100A<br>PE02-18-100A<br><br>Mazda 3 2.0L '12-'20<br>Mazda 6 2.5L '14-'20<br>MX-5 Miata 2.0L '16-'18<br>CX-5 '13-'14<br>CX-3 2.0L '16-'19 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC567** | **Audi / VW**<br>04C905110K<br>04E905110D<br>04E905110N<br><br>A1 1.0L TFSI '15-'18<br>A3 1.2L TFSI '13-'16<br>Q2 1.4T '18-'20<br>Polo T-Cross<br>Jetta 1.4T '13-'19 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC568** | **Honda**<br>30520-5A2-A01<br>UF-712<br><br>Accord 2.4L '13-'17<br>CR-V 2.4L '15-'19<br>Acura1 ILX 2.4L'16-'21<br>Acura1 TLX 2.4L'15-'20 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC569** | **Opel**<br>12580537<br>12580538<br>12567686<br><br>Vauxhall, Astra,<br>Vectra VX220<br>2.2L '05 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC570** | **Opel**<br>90564334<br>9195819, 9198834<br>1208213, 0221503031<br><br>Omega B '99-'03 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC571** | **Volvo**<br>9125601<br>30713416<br><br>S60, S70, S80<br>XC70, XC90,<br>V70<br>2.3L, 2.4L, 2.5L, 2.9L |

MOQ: 50pcs

# IGNITION COILS



| Part No.: | Application: |
|---|---|
| **PIC572** | **Volvo**<br>9135689<br>9146776<br>1275971<br><br>S90 2.9L '97-'98<br>S40 I 1.8L '99-'03<br>V90 Kombi 2.9L '97-'98<br>960 II 2.5L '94-'96<br>C70 I 2.5L '98-'05 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC573** | **Volvo**<br>1275602<br><br>S40 2.0T '03-'04<br>V40 2.0T '02-'04 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC574** | **Volvo**<br>30684245<br><br>XC60, V60,<br>S80, S60 (T6)<br>3.0L '15-'16 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC575** | **Volvo**<br>8687939<br><br>XC90, S80 4.4L V8<br>DOHC '05-'11 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC576** | **BYD / Mitsubishi**<br>F01R00A021<br>0221500802<br><br>BYD F3 L4-1.5L<br>Dongfeng Xiaokang 802<br>4G13 '05-'08 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC577** | **BYD**<br>F01R10A139<br>371QA-3705100<br>KRKTT15<br><br>F0 Geely<br>Panda, Cherry |

MOQ: 50pcs



2 Pins

| Part No.: | Application: |
|---|---|
| **PIC578** | **BYD / Hafei**<br>F01R00A011<br>F01R00A062<br><br>BYD F3 F3R<br>Southeast Ling Shuai<br>Hafei Horse Racing |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC579** | **BMW**<br>7575010-80, 12137562744<br>12138616153, 12137571643<br>12137551049, 12137575010<br>12137559842, 12137594596<br><br>BMW 1 '03-'13<br>BMW 2 '13-<br>BMW 3 '02-'16<br>335i GT L6 3.0L '14-'16<br>X3 '05-'11, X4 '13-<br>X5 '00-'16, X6 '07-'15 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC580** | **Changan**<br>F01R00A028<br><br>Chana- T10, T20, F30<br>BAIC M20, M30<br>Changan Star-Changue |

MOQ: 50pcs

# IGNITION COILS

| Part No.: | Application: |
|---|---|
| **PIC581** | **Suzuki / Changan**<br>3705010, 3705010E<br>SC6350B<br><br>Changan 460<br>JL466Q1<br>Changan Star 474<br>DongFeng EQ 474<br>BG13 1.3L |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC582** | **Suzuki / Changan**<br>33400D75F10E000<br>3705010-H01<br><br>Grand Vitara J24B 2.4L<br>Changan Cool Car |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC583** | **Changan**<br>F01R00A045<br><br>Haima 1.6 '07-'08<br>4G18 |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC584** | **Chery**<br>F01R00A041<br>E4G133705110<br><br>Cowin - Arizo 1.6VVT<br>Chery A3 M11<br>Tiggo 4G13, 4G16<br>Futian 469Q |

MOQ: 50pcs



| Part No.: | Application: |
|---|---|
| **PIC585** | **Chery**<br>F01R00A092<br>E4T163705110<br><br>Chery Tiggo 3X<br>Arrizo 5 1.5L |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC586** | **Chery**<br>F01R00A104<br>D4G15B-3705110<br><br>Tiggo 2X 1.5L<br>Tiggo 3X A13T 1.5L |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC587** | **Chery**<br>F01R00A023<br><br>QQ, QQ3<br>SQR371F 1.0L |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC588** | **Chery**<br>F01R00A024<br>Q21-3705110<br><br>Karry SQR472W |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC589** | **Geely**<br>3603040-28K<br>19080-T2A00<br><br>Geely MK,<br>FAW/Xenia M80 |

MOQ: 50pcs

# IGNITION COILS



| Part No.: | Application: |
|---|---|
| **PIC590**<br>**PIC555** | **Hyundai / Kia**<br>27301-03000<br>27301-03015<br>27301-03035<br><br>i10 1.2L '08-'13<br>i20 1.2L '08-'15<br>Santa Fe 2.7L '01-'06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC591** | **Lifan**<br>F01R00A061<br><br>330, 530, 620, 630,<br>720, X50, X60<br>1.3L, 1.5L, 1.8L '10- |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC592** | **Changan / Suzuki**<br>F01R00A030<br>F01R00A086<br>0221500802<br><br>Gazelle/Antelope 1.3L<br>(CS35, CS75)<br>Swift IV 1.6L<br>(AZG 416, AZH 416, RS416)<br>'12- M16A |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC593** | **Nissan**<br>22448-ZE00A<br>22448-ZE00C<br>UF-551<br><br>Infiniti QX56 5.6 V8<br>(VK56DE) '07-'10,<br>Armada 5.6 V8 07-'15,<br>Pathfinder 5.6 V8 '08-'12 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC594** | **Toyota**<br>90919-02254<br>90919-02261<br><br>Lexus GS460 '07-'11 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC595** | **Renault**<br>82005-68671<br><br>Clio2, Espace 3, 4<br>1.4L 16V |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC596** | **Toyota**<br>90919-A2009<br>90919-02276<br>UF-848<br><br>Lexus UX200 2.0L '19-<br>Camry 2.5L '18-'20<br>RAV4 2.5L L4 '19- |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC597** | **Honda**<br>30520-RN0-A01<br>UF-624<br><br>Accord V6 3.5L '08-'12<br>Crosstour V6 3.5L '10-'11<br>Odyssey '08-'16 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC598** | **Hyundai**<br>27300-3F100<br>27300-2G700<br>27300-2G000<br><br>Sonata, Santa Fe<br>2.4L '09-'14 |

MOQ: 50pcs

# IGNITION COILS



| Part No.: | Application: |
|---|---|
| **PIC599** | **Mercedes Benz**<br>A1561500080<br>A1561500380<br>A1569064400<br>A1569060500<br><br>C-Class (W204)<br>M-Class (W164) AMG<br>, |

MOQ: 50pcs



5-Pins

| Part No.: | Application: |
|---|---|
| **PIC600** | **Peugeot / Kia**<br>5WY 2847A<br><br>Peugeot 206, 405<br>Kia Tu5<br>(new model) |

MOQ: 50pcs

3-Pins

| Part No.: | Application: |
|---|---|
| **PIC601** | **Renault**<br>7700749450<br>7700858138<br>7702218697<br><br>Clio I 1.2L '96<br>19 Mk II 1,8L '94-'96<br>Twingo I 1.2L '93<br>Extra Van 1.2L '91 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC602** | **Peugeot / Citroen**<br>597085<br>9651710680<br><br>206/ 207/ 307 1.4L<br>Citroen C2, C3, C4 1.4L<br>'03-'06 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC603** | **Renault**<br>7700100589<br><br>Clio '98-'09<br>Kangoo '98-'03<br>Megane '99--03<br>Megane Scenic '99-'09 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC604** | **Renault**<br>7700100643<br><br>Clio '98-'08<br>Kangoo '98-'03<br>Megane '99--'03<br>Megane Scenic '89-'99 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC605** | **Mercedes Benz**<br>A000 158 77 03<br>1601587703<br><br>Smart Cabrio '02-'04<br>Smart City Coupe '03-'04<br>Smart Fortwo '04-'07<br>Smart Roadster '03-'05 |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC606** | **Nissan / Renault / Peugeot**<br>22448-00QAD<br>8200084401<br>H8200051128<br>8200064401<br><br>Kubistar 1.2L '06-'19<br>Clio, Kangoo,<br>Twingo 1.2L '00-<br>Peugeot 206 1.0L '00- |

MOQ: 50pcs

| Part No.: | Application: |
|---|---|
| **PIC607** | |

MOQ: 50pcs